

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CS/Smo20011909/UVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

PC 202fc

at Workshop m/s

CN motor

of

YN 5494E

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

621

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

aez 9k

Veh No:

PC 202fc

Yr Regn:

10 113

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota hiace H1Roof.c.c 2982

Colour

S.h

A/C: Insured / Std / NI / NA

Sp. Reading

103069

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFS T22P4000017655

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 n15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/10/20

D.O.I.

2/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/11/20 4/5 #700 Confirmed with MR Chew (Red 1106,61%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 6/11/20-typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: TP

Lump Sum / B.L. (\$ 700

TOTAL

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

31/10/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 29-10-2020

Estimated repair cost for vehicle no: PC2028C TOYOTA HIACE 3.0 A '13

CHASSIS: JTFST22P400017655

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet 707.85	✓	\$900.00
2	2	Front Bonnet Hinge 11 X	\$59.00	\$118.00
3	1	Front Bonnet Lock 11 X		\$98.00
4	1	Front Bonnet Emblem 68.50 11 ✓		\$90.00
Subtotal :-				\$1,206.00

Labour charges

Panel beating	120	\$300.00
Spray painting	200	\$300.00
Subtotal :-		\$600.00
Total:-		\$1,806.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-776.35
25.2
9-582.26
1-320.00
907.26
20%
171.