

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011911/ERA3Q2**Date:** 20/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100500854
Claimant Vehicle No :	SHC2735P	Insured Vehicle No :	SLL2055Z
Date of Loss:	31/10/2020	Nature of Claim:	TP
		Claim No:	4683129337SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2735P		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2F93573
Reg. Date:	13/12/2019 (Man. Year: 2019)	Chassis No:	JTDKB3FU103090174
Colour:	Blue	Odometer:	117701 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firestone 4 mm	Rear Left Side:	Firestone 4 mm
Front Right Side:	Firestone 4 mm	Rear Right Side:	Firestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,974.76	2,026.76	948.00	31.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	780.00	620.00	44.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,374.76	2,806.76	1,568.00	35.84
Approved Total (Overridden) (S\$)		2,806.75		
(S\$)	4,374.76	2,806.75	1,568.01	35.84
+ GST 7.00/7.00% (S\$)	306.23	196.47	109.76	35.84
Nett Amount (S\$)	4,680.99	3,003.22	1,677.77	35.84
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$126.47/day) (S\$)		252.94		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,358.16		

INSPECTION

Date of Assignment:	02/11/2020	
Date Inspected:	02/11/2020	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	945.30 FL	*945.30 FL
2	1		*FRT FENDER (HYBRID) LH	Necessary	86.50 FL	*86.50 FL
3	1		*FRONT DOOR LH	Repair	1,264.00 FL	*- FL
4	1		*FRT WHEEL RIM LH	Cut	1,570.55 FL	*1,570.55 FL
5	1		*FRT DOOR COMFORTDELGRO LH	Necessary	75.00 FS	*75.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,941.35	2,677.35
- List Item Discount on L Items 25.00/25.00% (S\$)					966.59	650.59
Total Parts (S\$)					2,974.76	2,026.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	320.00
2	SPRAYPAINT CHARGE	New	500.00	400.00
3	CHECK ALL LIGHTING	New	40.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	40.00	30.00
5	TRANFER OF DOOR	New	120.00	0.00
Gross Labour Cost (S\$)			1,400.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >