

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20011912/AGS3Q2

Date:

17/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900090396

Claimant Vehicle No : SLF5200H**Insured Vehicle No :**

SKU8606J

Date of Loss: 31/10/2020

Nature of Claim:

TP

Claim No:

7546676065SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLF5200H**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No:

3A92UDH5189

Reg. Date: 30/08/2016 (Man. Year: 2016)

Chassis No:

MMBSTA13AHH001873

Colour: Maroon

Odometer:

62018 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size:

185/55 R15

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,253.10	4,985.80	8,267.30	62.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,020.00	2,000.00	5,020.00	71.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,273.10	6,985.80	13,287.30	65.54
Approved Total (Overridden) (S\$)		5,500.00		

Nett Amount (S\$)	20,273.10	5,500.00	14,773.10	72.87
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		50.45		
Nett Liability (S\$)		6,050.45		

INSPECTION

Date of Assignment: 02/11/2020

Date Inspected: 03/11/2020

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	666.00 FL	*666.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	186.00 FL	*- FL
3	1		*FRONT BUMPER LOGO	Not Necessary	39.00 FL	*- FL
4	2		*FRONT BUMPER FOG LAMP	Not Necessary	786.00 FL	*- FL
5	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	240.00 FL	*- FL
6	1		*FRONT BUMPER TOP COVER GARNISH	Not Necessary	103.00 FL	*- FL
7	1		*FRONT BUMPER BOTTOM COVER GARNISH	Not Necessary	162.00 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER	Necessary	56.00 FL	*56.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	259.00 FL	*259.00 FL
10	1		*FRONT RADIATOR GRILLE	Cracked	525.00 FL	*525.00 FL
11	1		*HEADLAMP	O/S Cracked	1,312.00 FL	*656.00 FL
12	2		*FRONT FENDER INNER COWLING	Not Necessary	298.00 FL	*- FL
13	1		*BONNET LOCK BRACE PANEL	Not Necessary	89.00 FL	*- FL
14	1		*HORN	Not Necessary	99.00 FL	*- FL
15	1		*AIR CONDENSOR	Not Necessary	981.00 FL	*- FL
16	1		*RADIATOR	Not Necessary	872.00 FL	*- FL
17	1		*RADIATOR TOP BRACKET	Not Necessary	26.00 FL	*- FL
18	2		*RADIATOR MOUNTING	Not Necessary	72.00 FL	*- FL
19	1		*AIR DUCT	Cracked	109.00 FL	*109.00 FL
20	1		*REAR BUMPER	Deformed	646.00 FL	*646.00 FL
21	2		*REAR BUMPER REFLECTOR	Cracked	92.00 FL	*92.00 FL
22	2		*REAR BUMPER RETAINER	Necessary	62.00 FL	*62.00 FL
23	2		*REAR FENDER INNER COWLING	Not Necessary	202.00 FL	*- FL
24	2		*REAR FENDER INNER TRIM	Not Necessary	578.00 FL	*- FL
25	1		*REAR END PANEL AIR VENT	Cracked	57.00 FL	*57.00 FL
26	1		*REAR END PANEL AIR VENT COVER GARNISH	Cracked	147.00 FL	*147.00 FL
27	2		*TAILLAMP	Cracked	1,118.00 FL	*552.00 FL
28	1		*BOOTLID	Repair	828.00 FL	*- FL
29	1		*BOOTLID EMBLEM ATTRAGE	Necessary	29.00 FL	*29.00 FL
30	1		*BOOTLID EMBLEM MIVEC	Necessary	51.00 FL	*51.00 FL
31	1		*BOOTLID LOGO	Necessary	49.00 FL	*49.00 FL
32	4		*BOOTLID STOPPER	Not Necessary	44.00 FL	*- FL
33	2		*BOOT LID HINGE	Not Necessary	384.00 FL	*- FL
34	1		*BOOTLID TOP LOCK	Not Necessary	139.00 FL	*- FL
35	1		*BOOTLID LOWER LOCK	Not Necessary	47.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*BOOTLID WEATHERSTRIP	Cut	161.00 FL	*161.00 FL
37	1		*REAR END PANEL	Dented	449.00 FL	*449.00 FL
38	1		*REAR END PANEL TOP GARNISH	Cracked	97.00 FL	*97.00 FL
39	1		*REAR FLOOR PANEL TOP BOARD	Torn	299.00 FL	*299.00 FL
40	1		*FRONT NUMBER PLATE (OFF PEAK PLATE)	Necessary	120.00 FS	*50.00 FS
41	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
42	1		*SET FRONT RADIATOR GRILLE CLIP	Necessary	60.00 FS	*20.00 FS
43	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
44	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
45	1		*REAR NUMBER PLATE (OFF PEAK PLATE)	Necessary	120.00 FS	*50.00 FS
46	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
47	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
48	1		*BOOTLID EMBLEM C&C (SPECIAL TYPE)	Necessary	120.00 FS	*60.00 FS
49	1		*BOOTLID INNER RUBBER SEAL (SPECIAL TYPE)	Not Necessary	180.00 FS	*- FS
50	1		*SET TAILLAMP CLIPS	Necessary	40.00 FS	*20.00 FS
51	1		*SET REAR FENDER COWLING CLIP	Not Necessary	80.00 FS	*- FS
52	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
53	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
54	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
55	1		*REVERSE CAMERA	Not Necessary	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,489.00	5,482.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,235.90	496.20
Total Parts (\$)	13,253.10	4,985.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,200.00	300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	200.00
3	WIRING CHECK	New	180.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
6	REFOCUS HEADLAMP BEAM	New	60.00	0.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
8	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	600.00
9	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	600.00
10	TUFF COAT	New	250.00	60.00
11	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
12	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
13	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	0.00
14	TRANSFER BOOTLID MECHANISM	New	80.00	0.00
15	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
16	REMOVE AND RESEAL FRONT & REAR OFF PEAK PLATE	New	180.00	100.00
Gross Labour Cost (\$\$)			7,020.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >