

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20011917/R1CD3Q2  
**Date:** 10/03/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00055762001
Claimant Vehicle No :	SMP3203Z	Insured Vehicle No :	GBJ6701U
Date of Loss:	04/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D204116/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP3203Z	Engine No:	L13B3932273
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK33417782
Reg. Date:	20/09/2019 (Man. Year: 2019)	Odometer:	17837 km
Colour:	Grey		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/50R16	Rear Tyre Size:	205/50R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,798.57	1,227.05	1,571.52	56.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,725.00	910.00	815.00	47.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,523.57</b>	<b>2,137.05</b>	<b>2,386.52</b>	<b>52.76</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>316.65</b>	<b>149.59</b>	<b>167.06</b>	<b>52.76</b>
<b>Nett Amount (S\$)</b>	<b>4,840.22</b>	<b>2,286.64</b>	<b>2,553.58</b>	<b>52.76</b>

### INSPECTION

Date of Assignment:	02/11/2020		
Date Inspected:	12/11/2020	Inspected At:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD RASUL

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



3/10/2021

Adjuster Report

THE VEHICLE HAS NOT SEND IN FOR REPAIRS  
(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
<b>Parts:</b>	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMP3203Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH (WCP)	Bent	1,015.00 F	*1,015.00 F
2	1		*REAR DOOR FRAME STICKER RH (SET)(BLACK)(WCP)	Necessary	52.00 F	*52.00 F
3	1		*REAR FENDER RH (WCP)	Repair	1,085.00 F	*- F
4	1		*REAR FENDER INNER SHIELD RH (WCP)	Not Necessary	121.10 F	*- F
5	6		*REAR FENDER INNER SHIELD CLIPS (WCP)	Not Necessary	30.00 F	*- F
6	1		*REAR SPORT RIM RH	Repair	150.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>2,453.10</b>	<b>1,067.00</b>
<b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b>	345.47	160.05
<b>Total Parts (\$\$)</b>	<b>2,798.57</b>	<b>1,227.05</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILIATE REPAIR	New	700.00	350.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	35.00	0.00
3	TO SPRAY PAINT ON AFFECTED AREAS	New	600.00	400.00
4	SPRAY RUST PROOF ON AFFECTED AREA	New	40.00	40.00
5	TO TRANSFER ALL REAR RH DOOR FITTING	New	100.00	60.00
6	TO REMOVE & REFIT ALL NECESSARY TRIM BOARDS,GARNISH,CARPET,FLOOR MATS & SEAT	New	150.00	60.00
7	TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (\$\$)			<b>1,725.00</b>	<b>910.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >