

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011919/UBS3Q2

Date: 11/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800016772

Claimant
Vehicle No : SJS1047R **Insured Vehicle No :** SLW7304P

Date of Loss: 28/10/2020 Nature of Claim: TP Claim No: 3477966469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS1047R		
Make & Model:	HONDA CIVIC, 1.6 (A)	Engine No:	R16A14001761
Reg. Date:	29/07/2009 (Man. Year: 2008)	Chassis No:	JHMF46209S200555
Colour:	White	Odometer:	126012 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,196.96	6,021.12	2,175.84	26.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	2,850.00	740.00	20.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,786.96	8,871.12	2,915.84	24.74
Approved Total (Overridden) (\$\$)		7,000.00		
(\$\$)	11,786.96	7,000.00	4,786.96	40.61
+ GST 7.00/7.00% (\$\$)	825.09	490.00	335.09	40.61
Nett Amount (\$\$)	12,612.05	7,490.00	5,122.05	40.61
+ Car Rental (11.0 x S\$120.00/day) (\$\$)		1,320.00		
+ Doc/Search Fee (\$\$)		31.00		
Nett Liability (\$\$)		8,841.00		
Global Sum Settlement (\$\$)		8,800.00		

INSPECTION

Date of Assignment: 02/11/2020

Date Inspected: 02/11/2020 Inspected At:

Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Buckled	610.70 FL	*610.70 FL
2	2		*REAR BOOT HINGES	Repair	89.80 FL	*- FL
3	1		*REAR BOOT LOCK	Twisted	179.20 FL	*179.20 FL
4	1		*REAR BOOT LOCK CATCH	Not Necessary	18.90 FL	*- FL
5	1		*REAR BOOT RUBBER	Twisted	145.20 FL	*145.20 FL
6	1		*REAR BOOT CENTRE LOGO	Necessary	20.20 FL	*20.20 FL
7	2		*REAR BOOT REFLECTOR	Cracked	490.40 FL	*490.40 FL
8	1		*REAR NUMBER PLATE LAMP GARNISH	Torn	119.00 FL	*119.00 FL
9	2		*REAR NUMBE LAMP	Not Necessary	76.00 FL	*- FL
10	1		*REAR SPARE TYRE PANEL	Crumpled / Buckled	911.40 FL	*911.40 FL
11	1		*REAR SPARE TYRE TOP COVER BOARD	Distorted	427.20 FL	*316.00 FL
12	1		*REAR FENDER -LH	Repair	864.20 FL	*- FL
13	2		*REAR FENDER INNER SIDE GARNISH	Deformed / Torn	284.80 FL	*284.80 FL
14	1		*SET REAR FENDER INNER SIDE GARNISH CLIPSE	Necessary	33.00 FL	*33.00 FL
15	2		*REAR TAIL LAMP	Cracked	596.40 FL	*596.40 FL
16	1		*REAR TAIL LAMP PANEL	N/S Dented / O/S Repair	126.20 FL	*63.10 FL
17	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	48.40 FL	*- FL
18	1		*REAR END PANEL	Badly Dented	380.40 FL	*322.60 FL
19	1		*REAR END PANEL TOP GARNISH	Distorted	60.20 FL	*60.20 FL
20	1		*REAR WINDSCREEN MOULDING	Not Necessary	50.20 FL	*- FL
21	1		*REAR BUMPER	Distorted	638.00 FL	*638.00 FL
22	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	28.40 FL	*14.20 FL
23	1		*REAR EXHAUST SILENCER	Repair	526.20 FL	*- FL
24	2		*REAR EXHAUST RUBBER	Not Necessary	96.40 FL	*- FL
25	1		*REAR EXHAUST TOP HEAT COVER	Not Necessary	98.40 FL	*- FL
26	1		*REAR EXHAUST TOP GARNISH	Twisted	68.00 FL	*68.00 FL
27	2		*REAR EXHAUST TOP GARNISH CLIPSE	Not Necessary	11.00 FL	*- FL
28	1		*REAR BOOT SPOILER	Cracked	850.00 FS	*750.00 FS
29	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
30	1		*REAR SPARE TYRE PANEL TOP INSULATOR	Necessary	150.00 FS	*150.00 FS
31	1		*REAR WINDSCREEN GUM	Not Necessary	80.00 FS	*- FS
32	1		*REAR BUMPER SPOILER	Distorted	850.00 FS	*700.00 FS
33	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS
34	1		*REAR BOOT INNER TRIM	Deformed	189.20 FL	*189.20 FL
35	1		*REAR BOOT COVER CLIPSE	Not Necessary	44.00 FL	*- FL
36	1		*REAR BOOT HINGE COVER -LH	Torn	60.20 FL	*60.20 FL
37	1		*REAR BOOT RUBBER STOPPER	Torn	14.40 FL	*14.40 FL
38	1		*REAR STOOL SPONGE	Torn	90.20 FL	*90.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **9,676.20** **7,066.40**
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,479.24 1,045.28

Total Parts (\$\$) **8,196.96** **6,021.12**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	50.00	50.00
2	PANEL BEATING	New	1,800.00	1,500.00
3	CHECK WIRING	New	80.00	30.00
4	RUST PROOFING	New	80.00	60.00
5	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	0.00
6	TO REMOVE & REPLACE REAR BUMPER SENSOR	New	80.00	50.00
7	TO REMOVE & REPLACE REAR EXHAUST	New	80.00	60.00
8	TO REMOVE & REFIT SEAT AND UP -HOLD STEP	New	160.00	0.00
9	TO SPRAY PAINTING	New	1,100.00	1,100.00
Gross Labour Cost (\$)			3,590.00	2,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >