

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011922/KGS3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800082342	
Claimant Vehicle No : SMJ1623P	Insured Vehicle No : SJG6666J	
Date of Loss: 20/10/2020	Nature of Claim: TP	Claim No: 4125595601SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ1623P		
Make & Model: BMW 216I, 1.5 (A)	Engine No: 43195499B38A15A	
Reg. Date: 25/02/2019 (Man. Year: 2018)	Chassis No: WBA6V12080ED05747	
Colour: Metallic Silver	Odometer: 24271 km	
Engine Capacity: 1499 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17	Rear Tyre Size: 205/55 R17	
Front Left Side: Bridgestone 8 mm	Rear Left Side: Bridgestone 8 mm	
Front Right Side: Bridgestone 8 mm	Rear Right Side: Bridgestone 8 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,541.41	2,375.46	1,165.95	32.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	640.00	1,410.00	68.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,591.41	3,015.46	2,575.95	46.07
+ GST 7.00/7.00% (\$\$)	391.40	211.08	180.32	46.07
Nett Amount (\$\$)	5,982.81	3,226.54	2,756.27	46.07
+ Loss of Use (2.0 x \$50.00/day) (\$\$)		100.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		3,355.54		

INSPECTION

Date of Assignment: 03/11/2020		
Date Inspected: 02/11/2020	Inspected At:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair: 2.0 days		

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY -RH	Cut	2,495.75 FL	*2,495.75 FL
2	1		*FRONT BUMPER	Repair	997.25 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER -RH	Serviceable	115.25 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER -RH	Scratched	143.65 FL	*143.65 FL
5	4		*FRONT BUMPER SENSOR SEALS	Not Necessary	48.00 FL	*- FL
6	15		*FRONT BUMPER CLIPS	Not Necessary	135.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,934.90	2,639.40
- List Item Discount on L Items 10.00/10.00% (S\$)	393.49	263.94
Total Parts (S\$)	3,541.41	2,375.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR AND CHECK WIRING SYSTEM	New	100.00	0.00
2	TO PABEL BEAT LH FRONT FENDER ,LH FRONT BUMPER BRACKET ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME	New	800.00	200.00
3	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	800.00	240.00
4	TO RESET AND RE-PROGRAME HEADLAMP FAULT CODE	New	350.00	200.00
Gross Labour Cost (\$\$)			2,050.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >