

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20011924/KGS3Q2**Date:** 19/01/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
**Claimant**  
**Vehicle No :** SKZ7200B **Insured Vehicle No :** SHA4744K  
Date of Loss: 03/10/2020 Nature of Claim: TP Claim No: MCT20100061

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ7200B**  
Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1596890  
Reg. Date: 29/01/2016 (Man. Year: 2015) Chassis No: ZGE206024725  
Colour: Metallic White Odometer: 155967 km  
Engine Capacity: 1797 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18  
Front Left Side: Hankook 3 mm Rear Left Side: Hankook 3 mm  
Front Right Side: Hankook 3 mm Rear Right Side: Hankook 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	4,790.35	2,320.25	2,470.10	51.56	
Miscellaneous Items	0.00	0.00	0.00		
Labour	2,470.00	1,315.00	1,155.00	46.76	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>7,260.35</b>	<b>3,635.25</b>	<b>3,625.10</b>	<b>49.93</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>			
	(S\$)	7,260.35	3,500.00	3,760.35	51.79
<b>+ GST 7.00/7.00% (S\$)</b>		508.22	245.00	263.22	51.79
<b>Nett Amount (S\$)</b>	<b>7,768.57</b>	<b>3,745.00</b>	<b>4,023.57</b>	<b>51.79</b>	
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>			

INSPECTION

Date of Assignment: 02/11/2020  
Date Inspected: 04/11/2020 Inspected At: Optima Werkz Pte Ltd (HQ)  
6 Kung Chong Road  
Singapore 159143  
Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2021)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKZ7200B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	475.00 FL	*475.00 FL
2	1		*FOG LAMP LH	Serviceable	262.50 FL	*- FL
3	1		*FOG LAMP RH	Serviceable	262.50 FL	*- FL
4	1		*FOG LAMP COVER RH	Serviceable	112.50 FL	*- FL
5	1		*FOG LAMP COVER LH	Serviceable	112.50 FL	*- FL
6	1		*FRONT LOWER GRILLE LH	Serviceable	95.00 FL	*- FL
7	1		*FRONT LOWER GRILLE RH	Serviceable	95.00 FL	*- FL
8	1		*FRONT CENTER GRILLE	Serviceable	108.00 FL	*- FL
9	1		*FRONT CENTER GRILLE WITH CHROME	Serviceable	390.00 FL	*- FL
10	1		*HEADLAMP LH	Cracked	675.00 FL	*675.00 FL
11	1		*BONNET	Repair	630.00 FL	*- FL
12	1		*FRONT BUMPER UNDERCOVER	Serviceable	175.00 FL	*- FL
13	1		*ROCKER PANEL LH	*Check	375.00 FL	*- FL
14	1		*SIDE SKIRT LH	Cracked	684.00 FL	*684.00 FL
15	1		*FRONT WINDSCREEN		1,000.00 FL	*1,000.00 FL
16	1		*FRONT WINDSCREEN MOULDING	Necessary	125.00 FL	*125.00 FL
17	1		*FRONT DOOR GLASS LH	Serviceable	525.00 FL	*- FL
18	1		*SIDE MIRROR LH	*Check	91.80 FL	*- FL
19	1		*FRONT WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
20	1		*FRONT WINDSCREEN IU STICKER	Necessary	30.00 FS	*26.00 FS
21	1		*FRONT LICENSE PLATE WITH HOLDER	Cracked	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,338.80</b>	<b>3,060.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,548.45	739.75
<b>Total Parts (S\$)</b>	<b>4,790.35</b>	<b>2,320.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST ,DISMANTLE ACCIDENT AREA	New	800.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	1,000.00	800.00
3	LABOUR CHARGES TO REMOVE & REPLACE FRONT WINDSCREEN GLASS	New	150.00	0.00
4	LABOUR CHARGES TO REMOVE & REPLACE FRONT DOOR GLASS LH	New	150.00	0.00
5	LABOUR CHARGES TO DISCONNECT & RECONNECT FRONT WIRING SYSTEM & ETC	New	150.00	15.00
6	TO WHEEL ALIGNMENT & BALANCING	New	100.00	0.00
7	TO APPLY ANTI-RUST COATING TO AFFECTED AREA	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,470.00</b>	<b>1,315.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >