

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011930/UTD3Q2

Date: 01/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00092502001	
Claimant Vehicle No : SLM3407E	Insured Vehicle No : GBE5849K	
Date of Loss: 30/10/2020	Nature of Claim: TP	Claim No: SNM20D204117/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM3407E		
Make & Model: KIA FORTE K3, 1.6 SX (A)	Engine No: G4FGGH664876	
Reg. Date: 28/03/2017 (Man. Year: 2016)	Chassis No: KNAFZ411MH5694239	
Colour: White	Odometer: 59526 km	
Engine Capacity: 1591 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17	Rear Tyre Size: 225/45ZR17
Front Left Side: Nexen 6 mm	Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm	Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,768.00	11,101.00	7,667.00	40.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,660.00	10,380.00	5,280.00	33.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	34,428.00	21,481.00	12,947.00	37.61
Approved Total (Overridden) (\$\$)		14,000.00		
(\$\$)	34,428.00	14,000.00	20,428.00	59.34
+ GST 7.00/7.00% (\$\$)	2,409.96	980.00	1,429.96	59.34
Nett Amount (\$\$)	36,837.96	14,980.00	21,857.96	59.34

INSPECTION

Date of Assignment: 02/11/2020

Date Inspected: 03/11/2020 Inspected At:

Cycle & Carriage Fulco Motor Dealer
Pte Ltd (HQ)
330 Ubi Road 3
Singapore 408650

Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
Parts:	143	KIA FORTE K3 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM3407E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER-REAR BUMPER	Distorted	688.00 FS	*688.00 FS
2	1	*COVER-REAR BUMPER,CE	Distorted	315.00 FS	*315.00 FS
3	1	*COVER-RR BPR UNDER	Distorted	42.00 FS	*42.00 FS
4	4	*ULTRASONIC SENSOR AS	Serviceable	708.00 FS	*- FS
5	1	*WIRING HARNESS-BWS E	Not Necessary	216.00 FS	*- FS
6	1	*LH SIDE BRACKET-RE	Bent	29.00 FS	*29.00 FS
7	1	*RH SIDE BRACKET-RE	Bent	29.00 FS	*29.00 FS
8	10	*CLIP-REAR BUMPER	Necessary	20.00 FS	*20.00 FS
9	1	*BEAM-REAR BUMPER	Cracked	318.00 FS	*318.00 FS
10	2	*BRACKET-REAR BEAM	Necessary	10.00 FS	*10.00 FS
11	1	*BRACKET-REAR BEAM	Necessary	5.00 FS	*5.00 FS
12	1	*BRACKET-REAR BEAM	Necessary	3.00 FS	*3.00 FS
13	1	*BRACKET-REAR BEAM	Necessary	3.00 FS	*3.00 FS
14	1	*LH STAY-RR BUMPER	Not Necessary	120.00 FS	*- FS
15	1	*TRIM-TRANSVERSE RE	Twisted	58.00 FS	*58.00 FS
16	1	*WEATHERSTRIP-TRUNK	Twisted	100.00 FS	*100.00 FS
17	1	*RH STAY-REAR BUMPE	Not Necessary	120.00 FS	*- FS
18	1	*PANEL ASSY-BACK	Badly Dented	274.00 FS	*274.00 FS
19	1	*ANTENNA ASSY-SMARTKE	Not Necessary	69.00 FS	*- FS
20	1	*TRUNK LID PANEL ASSY	Dented/Buckled	1,365.00 FS	*1,365.00 FS
21	1	*LH HINGE ASSY-TRUNK	Bent	68.00 FS	*68.00 FS
22	1	*RH HINGE ASSY-TRUNK	Bent	68.00 FS	*68.00 FS
23	1	*LATCH ASSY-TRUNK L	Bent	112.00 FS	*112.00 FS
24	1	*LOGO ASSY-KIA SUB	Necessary	37.00 FS	*37.00 FS
25	1	*EMBLEM-CERATO	Necessary	35.00 FS	*35.00 FS
26	1	*FORTE EMBLEM	Necessary	40.00 FS	*40.00 FS
27	1	*EMBLEM K3	Necessary	15.00 FS	*15.00 FS
28	1	*RH LAMP ASSY-LICENSE	Not Necessary	18.00 FS	*- FS
29	1	*LH LAMP ASSY-LICEN	Not Necessary	18.00 FS	*- FS
30	1	*LH INSIDE LAMP ASSY	Cracked	710.00 FS	*710.00 FS
31	1	*RH INSIDE LAMP ASSY	Cracked	710.00 FS	*710.00 FS
32	1	*LH LAMP ASSY-REAR	Cracked	788.00 FS	*788.00 FS
33	1	*RH LAMP ASSY-REAR	Not Necessary	788.00 FS	*- FS
34	1	*SPOILER-REAR	Cracked	590.00 FS	*590.00 FS
35	1	*MOULDING-REAR WIND	Not Necessary	27.00 FS	*- FS
36	1	*GLASS ASSY-REAR WI	Not Necessary	534.00 FS	*- FS
37	1	*COVER-FRONT BUMPER	Distorted	633.00 FS	*633.00 FS
38	1	*KIA LOGO	Necessary	32.00 FS	*32.00 FS
39	1	*GRILLE ASSY-RADIAT	Cracked	328.00 FS	*328.00 FS
40	1	*MOULDING-FRONT BUM	Not Necessary	91.00 FS	*- FS
41	1	*MOULDING-FRONT BUM	Not Necessary	18.00 FS	*- FS
42	4	*ULTRASONIC SENSOR AS	Not Necessary	708.00 FS	*- FS
43	1	*WIRING HARNESS-FR BU	Not Necessary	237.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*ABSORBER-FRONT BUM	Torn	84.00 FS	*84.00 FS
45	1		*RAIL ASSY-FRONT BU	Not Necessary	496.00 FS	*- FS
46	1		*LH SIDE BRACKET-FR B	Necessary	13.00 FS	*13.00 FS
47	1		*RH SIDE BRACKET-FR	Necessary	13.00 FS	*13.00 FS
48	10		*CLIP-FRT BUMPER	Necessary	20.00 FS	*20.00 FS
49	1		*LH HEADLAMP ASSY	Holder Cracked	1,523.00 FS	*1,523.00 FS
50	1		*RH HEADLAMP ASSY	Cracked	1,523.00 FS	*1,523.00 FS
51	1		*CARRIER ASSY-FRONT	Not Necessary	675.00 FS	*- FS
52	4		*COOLANT	Not Necessary	104.00 FS	*- FS
53	1		*LH FENDER PANEL	Repair	435.00 FS	*- FS
54	1		*RH FENDER PANEL	Repair	435.00 FS	*- FS
55	1		*CONDENSER ASSY-COOLE	Not Necessary	681.00 FS	*- FS
56	1		*RADIATOR ASSY	Not Necessary	546.00 FS	*- FS
57	1		*BLOWER ASSY	Not Necessary	623.00 FS	*- FS
58	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
59	1		*REVERSE CAMERA LEN	Shorted	350.00 FS	*350.00 FS
60	2		*FRONT AND REAR NUMBER PLATE WITH CASING	Bent	100.00 FS	*100.00 FS
F=Franchise part. S=SpcNett.					Total Parts (\$\$)	18,768.00 11,101.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHTING AND WIRING SYSTEM ON FRT & RR ACCIDENT AFFECTED AREAS	New	100.00	100.00
2	TO REPLACE REAR WINDSCREEN GLASS	New	300.00	0.00
3	SEALANT KIT ON REAR WINDSCREEN GLASS	New	100.00	0.00
4	TO INSTALL RIKE COOL SOLAR FILM ON REAR WINDSCREEN GLASS	New	220.00	0.00
5	TO TRANSFER TRUNK LID COMPONENT AND MECHANISM PARTS	New	600.00	300.00
6	TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	600.00	300.00
7	TO REPLACE REAR BUMPER,REINFORCEMENT,ETC.-CUT ABD RE-WELD REAR END PANEL.-TO REPAIR REAR FLOORING AND BOTH REAR OTR QTR AND REAR TRACK PANEL.STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	4,800.00	3,300.00
8	TO APPLY SEALANT KIT ON NEW PANEL	New	300.00	200.00
9	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	2,940.00	2,100.00
10	TO REPLACE FRONT BUMPER,REINFORCEMENT,BOTH FRT FENDER,ETC.-TO REPLACE FRT CARRIER ASSY,STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS	New	3,600.00	2,400.00
11	SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS	New	2,100.00	1,680.00
Gross Labour Cost (\$\$)			15,660.00	10,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >