



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Ang Tiong Boon
	Reg No/Reg Date	SLM3407E*KC17S3/ 28/03/2017
	Date In/Mileage	30/10/2020/ 59526
	Chassis No	KNAFZ411MH5694239
	Engine No	G4FGGH664876
	Make/Model	KIA/CERATO K3 1.6 A SX ADQ
	Colour/Trim	SWP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	19/11/2020/ 09:13	DS	218 / Mars Ler	55705

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO CARRY OUT LUMP SUM REPAIR ON FRONT & REAR ACCIDENT AREA Z NOTES ACCIDENT ON 30/10/2020 ALONG BRAS BASAH RD TOWARDS NICOLL HIGHWAY OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR / L.O.U TP # GBE5849K TP INS : CHINA TAIPING				14000.00

Estimate

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Parts	0.00
Labour	0.00
Standard Menu	0.00
Specialist Job	14,000.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	14,000.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.