

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011931/AQF3Q2**Date:** 18/03/2021**REFERENCE**

Insured/Claimant: TAN JUN XIAN SHAWN Policy No: 2070149949
Date of Loss: 30/10/2020 Nature of Claim: OD Claim No: 6651637883SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV8306X**
Make & Model: AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A) Engine No: CZE866338
Reg. Date: 22/10/2020 (Man. Year: 2020) Chassis No: WAUZZZ8V8LA088972
Colour: Grey Odometer: 454 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$125,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,472.00	3,122.00	10,350.00	76.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,002.00	1,792.00	3,210.00	64.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,474.00	4,914.00	13,560.00	73.40
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	17,874.00	4,314.00	13,560.00	75.86
+ GST 7.00/7.00% (S\$)	1,251.18	301.98	949.20	75.86
Nett Amount (S\$)	19,125.18	4,615.98	14,509.20	75.86

INSPECTION

Date of Assignment: 02/11/2020

Date Inspected: 02/11/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,842.00 FS	*1,473.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	185.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	38.00 FS	*30.16 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	159.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Torn	293.00 FS	*234.40 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	293.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,406.00 FS	*1,124.80 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	189.00 FS	*- FS
9	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
10	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	186.00 FS	*- FS
12	1		*FRONT REINFORCEMENT BEAM	Not Necessary	715.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	187.00 FS	*- FS
14	1		*FOAM FILLER PIECE COVER	Not Necessary	121.00 FS	*- FS
15	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	197.00 FS	*- FS
16	1		*FRONT FENDER - LH	Repair	841.00 FS	*- FS
17	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - LH	Not Necessary	47.00 FS	*- FS
19	1		*FRONT FENDER BRACE	Not Necessary	95.00 FS	*- FS
20	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	61.00 FS	*- FS
21	1		*WHEEL HOUSING LINER - LH	Torn	167.00 FS	*133.20 FS
22	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	57.00 FS	*- FS
23	1		*LED HEADLIGHT - LH	Not Necessary	5,455.00 FS	*- FS
24	1		*LIFT CYLINDER - LH	Not Necessary	141.00 FS	*- FS
25	1		*LIFT CYLINDER HOSE	Not Necessary	67.00 FS	*- FS
26	1		*WASH WATER RESERVOIR	Not Necessary	202.00 FS	*- FS
27	1		*WASH WATER RESERVOIR PUMP	Not Necessary	151.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE - LH	Deformed	24.00 FS	*19.20 FS
29	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
30	1		*SUNDRIES	Necessary	200.00 FS	*30.16 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 13,472.00 3,122.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE ARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATUE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGAMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			5,002.00	1,792.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >