

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20011933/R1TD3E2

**Date:** 17/11/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNA00008782001	
Claimant Vehicle No :	SMS7841P	Insured Vehicle No :	PC4995Y	
Date of Loss:	31/10/2020	Nature of Claim:	TP	Claim No: SNM20D204119/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS7841P		
Make & Model:	BMW 520D, 2.0 (A)	Engine No:	F436K299B48B20A
Reg. Date:	13/03/2020 (Man. Year: 2019)	Chassis No:	WBAJR120X0CD73090
Colour:	Black	Odometer:	6541 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,422.25	6,719.40	2,702.85	28.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,971.00	2,342.00	629.00	21.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,393.25</b>	<b>9,061.40</b>	<b>3,331.85</b>	<b>26.88</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>867.53</b>	<b>634.30</b>	<b>233.23</b>	<b>26.88</b>
<b>Nett Amount (S\$)</b>	<b>13,260.78</b>	<b>9,695.70</b>	<b>3,565.08</b>	<b>26.88</b>

### INSPECTION

Date of Assignment:	02/11/2020	
Date Inspected:	04/11/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2020)
<b>Parts:</b>	143	BMW 520D 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMS7841P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH GRILLE INLET OPEN (LINES)	Serviceable	116.45 FS	*- FS
2	1		*FRT BUMPER CARRIER	Serviceable	726.70 FS	*- FS
3	1		*FRT BUMPER BOTTOM CARRIER	Serviceable	399.70 FS	*- FS
4	1		*RH FOG LAMP SUPPORT	Serviceable	65.00 FS	*- FS
5	1		*LH GUIDE TOP	Not Necessary	36.20 FS	*- FS
6	1		*RH GUIDE TOP	Serviceable	36.20 FS	*- FS
7	1		*LH BUMPER GUIDE	Not Necessary	16.95 FS	*- FS
8	1		*RH BUMPER GUIDE	Serviceable	16.95 FS	*- FS
9	1		*FRT BUMPER PANEL PRIMED (PMA/PDC)	Deformed	1,377.95 FS	*1,377.95 FS
10	1		*FRT BUMPER TOW HOOK COVER	Not Necessary	52.60 FS	*- FS
11	1		*RH HEADLIGHT LED AHL HIGH (CON LIG)	Cracked	4,879.55 FS	*4,879.55 FS
12	4		*DECOUPING RING PDC TORQUE CONVERTER	Serviceable	20.40 FS	*- FS
13	1		*PDC SENSOR SOPHISTOGRAU II WA90 (4 Pcs)	Scratched (1 Pc only)	1,527.60 FS	*381.90 FS
14	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
					<b>Total Parts (S\$)</b>	<b>9,422.25      6,719.40</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REPLACE FRONT BUMPER INCLUDE REMOVE ATTACHMENT ETC	New	1,275.00	850.00
2	SPRAY PAINTING FRONT BUMPER	New	1,038.00	934.00
3	TO REPLACE RIGHT HEAD LIGHT	New	481.00	408.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>2,971.00</b>	<b>2,342.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >