Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. :

b1 56428

Date Estimated :

02/11/2020

Prepared By :

Chua Kee Sin

- ESTIMATE REPAIR FOR -

- ACCOUNT -

135

Keow Hock Lye 21 Barker Road China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 309896

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

Grand Total:

MILEAGE

SMS7841P

WBAJR120X0CD73090

13/03/2020

520i

0

DESCRIPTION	ORIGINA	AL PRICE	DISC. %	NETT
To replace front bumper include remove attachment to facilitate repair caused by the accident.		850.00		850.00
To respray front bumper.		934.00		934.00
To replace right LED headlight.		408.00		408.00
To check electrical wiring system at the front section for proper function.		150.00		150.00
Sundries		80.00		80.00
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER PANEL PRIMED (PMA/PDC) RH HEADLIGHT LED AHL HIGH (ICON LIG PDC SENSOR SOPHISTOGRAU II WA90	1,377.95 4,879.55 381.90	1.00 1.00 1.00		1,377.95 4,879.55 381.90
SUPPLEMENTARY ITEMS	Total Labour :			2,422.00
	Total Parts:			6,639.40
		Total Labour & Parts :		9,061.40
	Deduction for Excess:			0.00
	Total Repair Costs less Excess:			9,061.40
	GST @7%:			634.30

9,695.70