

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20011935/EBS3Q2

**Date:** 29/12/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100486469  
**Claimant**  
**Vehicle No :** SH6607T **Insured Vehicle No :** SLG4898X  
Date of Loss: 31/10/2020 Nature of Claim: TP Claim No: 1769065184SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH6607T**  
Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU691205  
Reg. Date: 08/12/2016 (Man. Year: 2016) Chassis No: KMHLB41UMHU096658  
Colour: Blue Odometer: 380197 km  
Engine Capacity: 1685 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,134.80	0.00	1,134.80	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	480.00	200.00	29.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,814.80</b>	<b>480.00</b>	<b>1,334.80</b>	<b>73.55</b>
<b>+ GST 7.00/7.00% (S\$)</b>	127.04	33.60	93.44	73.55
<b>Nett Amount (S\$)</b>	<b>1,941.84</b>	<b>513.60</b>	<b>1,428.24</b>	<b>73.55</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (S\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$112.67/day) (S\$)</b>		338.01		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,003.61</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,000.00</b>		

#### INSPECTION

Date of Assignment: 02/11/2020  
Date Inspected: 02/11/2020 Inspected At: ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969  
Estimated Period of Repair: 2.0 days

---

**Adjuster:** CHEN TSUE YEE

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER ASSY -RR BUMPE	Repair	1,106.00 FL	*- FL	
2	1		*COVER -RR BUMPER LWR	Not Necessary	228.00 FL	*- FL	
3	10		*HYUNDAI BUMPER COVER CLIP	Not Necessary	22.00 FL	*- FL	
4	1		*PROTECTOR MAT	Not Necessary	50.00 FS	*- FS	
					<b>Sub Total (\$\$)</b>	<b>1,406.00</b>	<b>0.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	271.20	0.00
					<b>Total Parts (\$\$)</b>	<b>1,134.80</b>	<b>0.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT CHARGE	New	300.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >