



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : SNM20D204118/C01/LEWLC

Date: 06th Nov 2020

Our Ref : CS/CTI20011942/Ksd3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMK 763U
ACCIDENT ON 29/10/2020**

Instruction was received to inspect the vehicle Reg. No. SMK 763U. The inspection was conducted on 03/11/2020 at the premises of M/s Ding Auto Pte Ltd, Blk 10, #01-20, Sin Ming Industrial Estate Sector C, Singapore 575645.

The following vehicle information was recorded:

Registration Number : SMK 763U
Make/Model : Volvo S60 T4 1.6 AT ABS D/AB 2WD 4DR TC
Year of Registration : 2011
Body Colour : White
Chassis Number : YV1FS485BC2093096
Engine Capacity : 1596 cc
Speedometer Reading : 151576 km

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$18,250.67 (Sin Dollars: Eighteen Thousand Two Hundred Fifty and Sixty Seven Cents only.) (Exclude check items S\$3,840.00Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value	S\$ 30,500.00
<i>Less: LTA Reimbursement Value (RV)</i>	(S\$ 25,052.00)
	<u>S\$ 5,448.00</u>
<i>Less: Excess</i>	<u>(S\$ 100.00)</u>

Nett Liability S\$ 5,348.00

(b) If the vehicle to be "Repair"

Repair Cost (Est) (Exclude check items S\$3,840.00Nett)	S\$ 18,250.67
<i>Less: Excess</i>	(S\$ 100.00)

Nett Liability S\$ 18,150.67

(a) - (b) = (S\$ 12,802.67)
=====

The amount of estimated saving of S12,802.67 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:

KONG SENG CHEONG
Licensed Appraiser

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.