

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909**Our File No:** CS/CTI20011942/KSD3E2**Date:** 06/11/2020REFERENCE

Insured/Claimant: TOH WEE FONG Policy No: DMPCSNW00068042000

Date of Loss: 29/10/2020 Nature of Claim: OD Claim No: SNM20D204118/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMK763U</b>	Engine No:	B4164T1041313
Make & Model:	VOLVO S60, 1.6 T4 (A)	Chassis No:	YV1FS485BC2093096
Reg. Date:	27/12/2011 (Man. Year: 2011)	Odometer:	151576 km
Colour:	White		
Engine Capacity:	1596 cc		
Market Value/New Car Price:	S\$30,500.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	21,535.00	17,045.00	4,490.00	20.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	856.80	730.80	126.00	14.71
Paintwork Labour	474.87	474.87	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,866.67</b>	<b>18,250.67</b>	<b>4,616.00</b>	<b>20.19</b>
<b>- Excess (S\$)</b>	0.00	100.00	-100.00	
<b>(S\$)</b>	22,866.67	18,150.67	4,716.00	20.62
<b>+ GST 7.00/0.00% (S\$)</b>	1,600.67	0.00	1,600.67	100.00
<b>Nett Amount (S\$)</b>	<b>24,467.34</b>	<b>18,150.67</b>	<b>6,316.67</b>	<b>25.82</b>

INSPECTION

Date of Assignment: 02/11/2020 Present Location:

Date Inspected: 03/11/2020 Inspected At:

Ding Auto Pte Ltd (HQ)

Ding Auto Pte Ltd (HQ)

Blk 10, #01-20, Sin Ming Industrial Estate  
Sector C

Singapore 575645

Estimated Period of Repair: 12.0 days

**Adjuster:** KENNETH KONG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(EXCLUDE CHECK ITEMS S\$3,840.00 NETT)

**TOTAL LOSS ASPECT**

Market Value :	\$30,500.00
OMV :	\$35,116.00
PARF Rebate (1) :	\$19,313.00
Quota Premium Paid :	\$50,001.00
COE Rebate (2) :	\$5,739.00
Total Rebate (1) + (2) = :	\$25,052.00

The total amount incurred will be Market Value \$30,500.00 minus Total Rebate \$25,052.00 = \$5,448.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2020)
<b>Parts:</b> 143	VOLVO S60 1.6 T4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMK763U)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		<b>*TOTAL PARTS</b>		21,535.00 F	*16,895.00 F	
2	1		<b>*L/F TYRE 215/60 R 16..V (\$250.00) (60%)</b>	Punctured	-	*150.00 FS	
					<b>Total Parts (S\$)</b>	<b>21,535.00</b>	<b>17,045.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	298.20	298.20
2	Total Paint Materials	New	176.67	176.67
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	856.80	730.80
			<b>Gross Labour Cost (\$)</b>	<b>1,331.67</b>
				<b>1,205.67</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >