

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20011947/R1BA3Q2

Date: 27/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100305286

Claimant
Vehicle No : SLC7721Z **Insured Vehicle No :** SDZ3001T

Date of Loss: 01/11/2020 Nature of Claim: TP Claim No: 1178614206SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC7721Z		
Make & Model:	VOLKSWAGEN GOLF, 1.2 TSI (A)	Engine No:	CYV064218
Reg. Date:	25/05/2016 (Man. Year: 2015)	Chassis No:	WVWZZZAUZGW126576
Colour:	Blue	Odometer:	84462 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,847.86	4,388.88	10,458.98	70.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,300.00	13,500.00	10,800.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	39,147.86	17,888.88	21,258.98	54.30
+ GST 7.00/7.00% (S\$)	2,740.35	1,252.22	1,488.13	54.30
Nett Amount (S\$)	41,888.21	19,141.10	22,747.11	54.30
+ Loss of Use (21.0 x S\$60.00/day) (S\$)		1,260.00		
		Nett Liability (S\$)	20,401.10	

INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 03/11/2020 Inspected At:

17 TUAS AVE 9
Repairer: VOLKSWAGEN GROUP
SINGAPORE PTE LTD

Estimated Period of Repair: 15.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*A/C GAS	Not Necessary	60.00 FS	*- FS
2	1		*HECKKLAPPE REAR LID	Serviceable	2,004.17 FS	*- FS
3	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKE LIGHT	Serviceable	158.79 FS	*- FS
4	1		*WASSERABLAUF SCHLAUCH WATER DRAINAGE HOSE	Missing	11.40 FS	*7.98 FS
5	1		*GASKET REAR WEATHERSTRIP	Serviceable	260.93 FS	*- FS
6	2		*GROMMET	Not Necessary	29.34 FS	*- FS
7	1		*1K WINDOW ADHESIVE	Not Necessary	99.02 FS	*- FS
8	1		*ALL PURPOSE CLEANER	Not Necessary	89.22 FS	*- FS
9	1		*PRIMER	Not Necessary	25.74 FS	*- FS
10	1		*ACTIVATOR FOR PRECOATED W	Not Necessary	23.77 FS	*- FS
11	2		*APPLICATOR	Not Necessary	18.78 FS	*- FS
12	1		*INSCRIPTION BRIGHT CHROME LOGO -GOLF	Necessary	77.15 FS	*54.01 FS
13	1		*INSCRIPTION PURE WHITE/PO LOGO-BLUEMOTION	Necessary	77.56 FS	*54.29 FS
14	1		*INSCRIPTION BRIGHT CHROME LOGO-TSI	Necessary	69.85 FS	*48.90 FS
15	1		*COVER FOR BUMPER PRIMED	Deformed	1,165.55 FS	*815.89 FS
16	1		*REAR DIFFUSOR SATIN BLACK SPOILER	Deformed	323.62 FS	*226.53 FS
17	1		*RIVET (6 PCS)	Necessary	6.54 FS	*4.58 FS
18	1		*BUMPER REINFORCEMENT	Bent	619.61 FS	*433.73 FS
19	1		*ATTACHMENT STRIP REAR BUMPER CTR BRACKET	Cracked	64.97 FS	*45.48 FS
20	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Cracked	37.46 FS	*26.22 FS
21	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Serviceable	37.46 FS	*- FS
22	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Serviceable	37.46 FS	*- FS
23	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Serviceable	37.46 FS	*- FS
24	2		*LICENSE PLATE LIGHT	Serviceable	76.02 FS	*- FS
25	2		*FLAT CONTACT HOUSING WITH NUMBER PLATE LIGHT WIRE HOUSING	Serviceable	20.70 FS	*- FS
26	1		*REFLECTOR LH	Serviceable	71.19 FS	*- FS
27	1		*REFLECTOR RH	Serviceable	71.19 FS	*- FS
28	1		*END PANEL END PANEL OUTER	Repair	121.41 FS	*- FS
29	1		*ZINC SPRAY	Not Necessary	62.88 FS	*- FS
30	1		*2K-BODY ADHESIVE	Not Necessary	406.76 FS	*- FS
31	1		*SEALANT CAN BE SPRAYED	Not Necessary	61.67 FS	*- FS
32	6		*WELD STUD	Not Necessary	5.28 FS	*- FS
33	1		*HEAT SHIELD FOR EXHAUST M	Bent	142.50 FS	*99.75 FS
34	1		*EXHAUST SILENCER REAR	Serviceable	1,009.60 FS	*- FS
35	1		*DUAL CLAMP	Necessary	57.56 FS	*40.29 FS
36	1		*HOOD FRT BONNET	Repair	1,131.64 FS	*- FS
37	1		*HOOD LATCH BONNET LOCK	Serviceable	255.59 FS	*- FS
38	1		*CABLE HOOD LATCH LOCK CABLE	Serviceable	33.99 FS	*- FS
39	1		*COVER FOR BUMPER PRIMED FRT BUMPER	Deformed	1,158.63 FS	*811.04 FS
40	1		*SUPPORT PART BUMPER INNER BRACKET LH	Serviceable	54.69 FS	*- FS
41	1		*SUPPORT PART BUMPER INNER BRACKET RH	Serviceable	54.69 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Serviceable	20.91 FS	*- FS
43	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Serviceable	20.91 FS	*- FS
44	1		*FOAM INSERT	Cracked	41.99 FS	*29.39 FS
45	1		*IMPACT BEAM FRT REINFORCEMENT	Bent	619.61 FS	*433.73 FS
46	1		*RADIATOR GRILLE SATIN BLA	Cracked	472.52 FS	*330.76 FS
47	1		*TWIN HALOGEN HEADLAMPS H/LAMP LH	Serviceable	725.37 FS	*- FS
48	1		*TWIN HALOGEN HEADLAMPS H/LAMP RH	Scratched	725.37 FS	*507.76 FS
49	1		*FLAT CONTACT HOUSING H/LAMP WIRE HOUSING	Serviceable	38.38 FS	*- FS
50	1		*LOCK CARRIER WITH MOUNTIN	Serviceable	1,144.12 FS	*- FS
51	1		*SUPPORT FOR LOCK CARRIER	Cracked	43.22 FS	*30.25 FS
52	1		*GUIDE FRT BUMPER CTR BRACKET	Cracked	39.74 FS	*27.82 FS
53	1		*CROSS SUPPORT H/LAMP TOP PANEL LH	Bent	36.06 FS	*25.24 FS
54	1		*CROSS SUPPORT H/LAMP TOP PANEL RH	Bent	36.06 FS	*25.24 FS
55	2		*COOLANT	Not Necessary	41.76 FS	*- FS
56	1		*REAR WATER LEAK TEST	Necessary	150.00 FS	*150.00 FS
57	1		*REVERSE SENSOR	Serviceable	400.00 FS	*- FS
58	1		*FRT NUMBER PLATE	Scratched	80.00 FS	*80.00 FS
59	1		*REAR NUMBER PLATE	Missing	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 14,847.86 4,388.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	LEAKAD CHECK ,VACUUM & REGAS	New	420.00	0.00
4	LABOUR FRT	New	5,040.00	1,680.00
5	SPRAY PAINT FRT	New	3,200.00	1,600.00
6	LABOUR REAR	New	6,720.00	4,200.00
7	SPRAY PAIN REAR	New	4,800.00	4,000.00
8	R&R REAR W/SCREEN	New	840.00	0.00
9	R&R REAR LUGGAGE TRIM	New	840.00	420.00
10	TRANSFRT BOOT LID MECHANISM	New	840.00	420.00
11	R&R REAR EXHAUST PIPE	New	840.00	420.00
Gross Labour Cost (\$\$)			24,300.00	13,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >