

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20011959/DBS3Q2

Date:

31/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SJH707J

Date of Loss: 30/10/2020

Policy No:

0100552436

Insured Vehicle No :

SDJ2277E

Nature of Claim:

TP

Claim No:

9918518817SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJH707J**

Make & Model: HONDA FIT, 1.3 G (A)

Reg. Date: 25/07/2008 (Man. Year: 2008)

Colour: Blue

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: L13A4084773

Chassis No: GE61075387

Odometer: 222134 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Handbrake (Serviceable):

Yes

Steering (Serviceable):

Engine Modification:

Yes

No

Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Front Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

195/55 R15

Hankook 5 mm

Hankook 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,444.40	0.00	10,444.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	600.00	3,420.00	85.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,464.40	600.00	13,864.40	95.85
+ GST 7.00/7.00% (S\$)	1,012.51	42.00	970.51	95.85

Nett Amount (S\$)	15,476.91	642.00	14,834.91	95.85
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	03/11/2020		
Date Inspected:	03/11/2020	Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	2.0 days		

Adjuster:	BRYAN TANI	Manager:	CHUA ZHEN LI
------------------	------------	-----------------	--------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Necessary	985.00 FL	*- FL
2	1		*TAILGATE LOCK	Not Necessary	289.00 FL	*- FL
3	1		*TAILGATE INNER TRIM	Not Necessary	486.50 FL	*- FL
4	1		*TAILGATE WINDSCREEN MOULDING	Not Necessary	110.00 FL	*- FL
5	1		*TAILGATE HONDA LOGO	Not Necessary	85.00 FL	*- FL
6	1		*TAILGATE FIT EMBLEM	Not Necessary	82.00 FL	*- FL
7	1		*REAR BUMPER	Repair	758.00 FL	*- FL
8	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	92.00 FL	*- FL
9	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.30 FL	*- FL
10	2		*TAIL LAMP L+R	Not Necessary	1,196.40 FL	*- FL
11	2		*TAIL LAMP PANEL L+R	Not Necessary	970.60 FL	*- FL
12	1		*REAR END PANEL	Not Necessary	498.60 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	298.20 FL	*- FL
14	1		*REAR FENDER L+R	O/S Repair /N/S Not Necessary	2,659.60 FL	*- FL
15	2		*REAR FENDER INNER TRIM L+R	Not Necessary	685.80 FL	*- FL
16	1		*SPARE WHEEL PANEL	Not Necessary	893.40 FL	*- FL
17	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	699.20 FL	*- FL
18	2		*SPARE WHEEL QUARTER PANEL L+R	Not Necessary	998.40 FL	*- FL
19	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	389.50 FL	*- FL
20	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
21	1		*SET REAR REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
22	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
23	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
24	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
25	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,885.50	0.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,441.10	0.00
Total Parts (\$\$)	10,444.40	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,000.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,000.00	300.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO RNR REVERSE CAMERA	New	100.00	0.00
6	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	New	250.00	0.00
7	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	0.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
9	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
11	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	0.00
Gross Labour Cost (S\$)			4,020.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >