

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011960/AGS3Q2
Date: 25/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100505409
Claimant Vehicle No :	SKS514D	Insured Vehicle No :	SLM3407E
Date of Loss:	30/10/2020	Nature of Claim:	TP
		Claim No:	8125910719SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS514D		
Make & Model:	NISSAN JUKE, 1.6 (A)	Engine No:	HR16411086R
Reg. Date:	24/03/2015 (Man. Year: 2015)	Chassis No:	SJNFBAF15U7088544
Colour:	Red	Odometer:	86823 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,091.72	1,836.88	3,254.84	63.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,625.00	930.00	1,695.00	64.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,716.72	2,766.88	4,949.84	64.14
Approved Total (Overridden) (S\$)		2,200.00		

(S\$)	7,716.72	2,200.00	5,516.72	71.49
Nett Amount (S\$)	8,256.89	2,354.00	5,902.89	71.49
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,784.00		

INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 03/11/2020

Estimated Period of Repair: 3.0 days

Inspected At:

SK Automobile Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre
 Singapore 415933

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP LH/RH	Not Necessary	755.40 FL	*- FL
2	1		*REAR TAILLAMP LOWER BRACKET LH/RH	Not Necessary	83.60 FL	*- FL
3	2		*REAR FENDER ARCH GARNISH LH/RH	Cracked	966.00 FL	*537.20 FL
4	1		*REAR BUMPER	Deformed	577.20 FL	*577.20 FL
5	1		*REAR BUMPER JUKE EMBLEM	Necessary	73.60 FL	*73.60 FL
6	1		*REAR BUMPER LOWER DIFFUSER	Distorted	288.80 FL	*288.80 FL
7	1		*REAR BUMPER 3RD BRAKE LAMP	Cut	155.80 FL	*155.80 FL
8	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	132.00 FL	*- FL
9	2		*REAR BUMPER SIDE RETAINER LH/RH	Necessary	85.60 FL	*85.60 FL
10	1		*REAR BUMPER INNER SIDE SHIELD LH/RH	O/S Torn	78.40 FL	*39.20 FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	491.10 FL	*- FL
12	1		*REAR BUMPER INNER SPONGE	Cracked	110.80 FL	*110.80 FL
13	1		*REAR END PANEL	Not Necessary	427.90 FL	*- FL
14	1		*REAR END PANEL INNER TOP GARNISH	Not Necessary	83.60 FL	*- FL
15	1		*REAR EXHAUST SILENCER BOX	Repair	688.00 FL	*- FL
16	3		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	48.00 FL	*- FL
17	1		*REAR BUMPER LOWER COVER	Torn	95.00 FL	*95.00 FL
18	2		*REAR TAILLAMP CLIPS SET LH/RH	Not Necessary	80.00 FS	*- FS
19	2		*REAR FENDER ARCH GARNISH CLIPS SET LH/RH	Necessary	120.00 FS	*40.00 FS
20	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
21	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
23	1		*REAR EXHAUST GASKET	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,605.80	2,033.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	514.08	196.32
Total Parts (\$\$)	5,091.72	1,836.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	800.00	400.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	800.00	350.00
3	TO APPLY ANTI-RUST & TUFF-KOTE	New	75.00	20.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO PERFORM TRANSFER REAR TAILGATE MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	New	250.00	0.00
6	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	50.00
7	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	New	180.00	80.00
8	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	0.00
9	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (\$\$)			2,625.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >