

$\mathbb{Q} \subset \mathbb{R} \subset \mathbb{C}$

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

194

PAR Automotive Consultancy

Regn No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0451-19-TCA

14 October 2019

ACCIDENT VEHICLE SURVEY REPORT

Keok Su Seng
Blk 893A Woodlands Drive 50 #10-123
Singapore 730893

VEHICLE INFORMATION:

Vehicle Reg No.:	SMD9330M	Odometer:	10569km
Make & Model:	Audi Q2	Colour:	Grey
Chassis number:	WAUZZZGA0JA084734	Date of accident:	04/02/2019
Year of Regn.:	12/09/2018	Date inspected:	18/02/2019
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	26/02/2019

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Bridgestone	6mm/Bridgestone	215/55R17
Rear:	6mm/Bridgestone	6mm/Bridgestone	215/55R17

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the top portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
FRONT WINDSCREEN GLASS MOULDING	1	necessary	913.00	913.00
ROOF TOP PANEL	1	buckled	2,919.00	2,919.00
ROOF TOP PANEL INSULATOR MAT	1	necessary	572.00	572.00
ROOF TOP PANEL LINING	1	deformed	1,809.00	1,809.00
Subtotal before discount			S\$ 6,213.00	S\$ 6,213.00
Percentage discount 0% and 5%			S\$ 0.00	S\$ 310.65
Sub-total 1			S\$ 6,213.00	S\$ 5,902.35
CENTER PILLAR INNER TRIM GARNISH CLIPS L/R - SET	2	necessary	60.00	60.00
FRONT DOOR PILLAR INNER TRIM GARNISH CLIPS L/R - SET	2	necessary	60.00	60.00
FRONT WINDSCREEN GLASS SEALANT	1	necessary	100.00	100.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	2	necessary	100.00	100.00
REAR FENDER INNER TRIM UPPER TRIM GARNISH CLIPS L/R - SET	2	necessary	60.00	60.00
ROOF TOP PANEL LINING CLIPS - SET	1	necessary	50.00	50.00
Subtotal before discount			S\$ 430.00	S\$ 430.00
Sub-total 2			S\$ 430.00	S\$ 430.00
Parts-total			S\$ 6,643.00	S\$ 6,332.35

LABOUR

To remove, change air bag, air-bag sensor, air-bag wire and resetting system.	800.00	800.00
To reset system after repair works	500.00	500.00
To remove, reinstall windscreen. (to FR)	150.00	120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	300.00	150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,200.00	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,300.00	1,100.00
To apply anti-rust chemical on repaired and replaced panel.	100.00	60.00
Labour Total	S\$ 4,350.00	S\$ 3,730.00
Parts & Labour Total	S\$ 10,993.00	S\$ 10,062.35

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 8,600.00
and the recommended number of working days for the repairs is within 9 day(s).



B J Loi (I Eng., MIM, AIRTE)
Automotive Appraiser