

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011964/QGS3Q2
Date: 16/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800000246
Claimant Vehicle No :	SLQ374P	Insured Vehicle No :	SLV6312C
Date of Loss:	30/10/2020	Nature of Claim:	TP
		Claim No:	4734797453SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ374P		
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Engine No:	2ZRS054205
Reg. Date:	27/06/2017 (Man. Year: 2017)	Chassis No:	JTDMKB3FU103560655
Colour:	Silver	Odometer:	158144 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,284.75	3,038.25	246.50	7.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	900.00	800.00	47.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,984.75	3,938.25	1,046.50	20.99
Approved Total (Overridden) (S\$)		3,150.00		

(S\$)	4,984.75	3,150.00	1,834.75	36.81
+ GST 7.00/7.00% (S\$)	348.93	220.50	128.43	36.81
Nett Amount (S\$)	5,333.68	3,370.50	1,963.18	36.81
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
(S\$)		3,770.50		
Liabe Amount (80.00%) (S\$)		3,016.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,018.40		
Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 03/11/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/R FENDER	Dented	933.10 FL	*933.10 FL
2	1		*F/R FENDER INNER LINER	Serviceable	49.70 FL	*- FL
3	1		*F/L FENDER HYBRID EMBLEM	Serviceable	52.30 FL	*- FL
4	1		*F/R FENDER HYBRID EMBLEM	Necessary	52.30 FL	*52.30 FL
5	1		*F/R HEADLAMP	Cracked	2,530.10 FL	*2,530.10 FL
6	1		*FRONT BUMPER	Crumpled	495.50 FL	*495.50 FL
7	1		*SET BUMPER AND FENDER LINER CLIPS	Necessary	200.00 FS	*30.00 FS
					Sub Total (\$)	4,313.00
					- List Item Discount on L Items 25.00/25.00% (\$)	1,028.25
					Total Parts (\$)	3,284.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING F/R FENDER ,FRONT BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	New	900.00	500.00
2	TO RESPRAY FRONT BUMPER AND F/R FENDER	New	800.00	400.00
Gross Labour Cost (\$\$)			1,700.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >