

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20011965/USD3Q2

**Date:** 08/01/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00087752000
<b>Claimant Vehicle No :</b>	SLV6353J	<b>Insured Vehicle No :</b>	SLX9638H
Date of Loss:	30/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D204113C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV6353J	Engine No:	R16B22001228
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	MRHFC5650HT000796
Reg. Date:	08/01/2018 (Man. Year: 2017)	Odometer:	39703 km
Colour:	White		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,399.16	695.72	703.44	50.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	2,285.00	1,695.00	42.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,379.16</b>	<b>2,980.72</b>	<b>2,398.44</b>	<b>44.59</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	376.54	208.65	167.89	44.59
<b>Nett Amount (\$\$)</b>	<b>5,755.70</b>	<b>3,189.37</b>	<b>2,566.33</b>	<b>44.59</b>

### INSPECTION

Date of Assignment:	03/11/2020		
Date Inspected:	09/11/2020	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jan 2021)
<b>Parts:</b>	143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV6353J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY,RR BUMPER	Dented/Deformed	586.34 F	*586.34 F
2	1		*BEAM COMPRR.BUMPER	Repair	171.00 F	*- F
3	1		*GARNISH,RR BUMPER LOWER	Grazed	37.81 F	*37.81 F
4	1		*SPACERR,RR BUMPER SIDE	Not Necessary	10.92 F	*- F
5	1		*SPACERL,RR BUMPER SIDE	Not Necessary	10.92 F	*- F
6	1		*CLIP,BUMPER (7 Pcs)	Necessary	15.29 F	*15.29 F
7	1		*EMBLEM SETRR	Necessary	12.25 F	*12.25 F
8	1		*EMBLEMRR	Necessary	11.40 F	*11.40 F
9	1		*EMBLEM,H-MARK	Necessary	12.63 F	*12.63 F
10	2		*NUTPUSH 3MM	Not Necessary	3.99 F	*- F
11	1		*ANTENNA ASSYL.F	Not Necessary	57.76 F	*- F
12	1		*BUZZER ASSYSMART	Not Necessary	59.75 F	*- F
13	1		*LOCK ASSYTRUNK	Not Necessary	77.14 F	*- F
14	2		*SENSOR ASSY PARKING	Serviceable	281.96 F	*- F
15	1		*SUNDRIES	Necessary	50.00 F	*20.00 F
F=Franchise part.						
<b>Total Parts (\$\$)</b>					<b>1,399.16</b>	<b>695.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	150.00	120.00
2	REMOVE & INSTALL REVERSE SENSORS-4 PCS	New	180.00	150.00
3	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	0.00
4	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	1,500.00	975.00
5	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)	New	1,700.00	1,040.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,980.00</b>	<b>2,285.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >