

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011966/KCD3E2

Date: 27/04/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00089012000
Claimant Vehicle No : SKQ1195U **Insured Vehicle No :** SBG4D
Date of Loss: 29/10/2020 Nature of Claim: TP Claim No: SNM20D204129/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ1195U**
Make & Model: LEXUS ES250, 2.5 (A) Engine No: 2ARE905076
Reg. Date: 03/11/2014 (Man. Year: 2014) Chassis No: JTHBJ1GG602063394
Colour: Metallic Grey Odometer: 89977 km
Engine Capacity: 2494 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,548.00	3,393.00	155.00	4.37
Miscellaneous Items	135.00	135.00	0.00	0.00
Labour	277.20	277.20	0.00	0.00
Paintwork Labour	500.86	500.86	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,461.06	4,306.06	155.00	3.47
+ GST 7.00/7.00% (S\$)	312.27	301.42	10.85	3.47
Nett Amount (S\$)	4,773.33	4,607.48	165.85	3.47

INSPECTION

Date of Assignment: 03/11/2020 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 03/11/2020 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2021)
Parts:	143	LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ1195U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		3,548.00 F	*3,393.00 F
F=Franchise part.						
Total Parts (S\$)					3,548.00	3,393.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Extra	135.00	135.00
Sub Total (\$\$)			135.00	135.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Including Material	New	500.86	500.86
<u>Labour Items</u>				
2	Total of Labour	New	277.20	277.20
Gross Labour Cost (\$\$)			778.06	778.06

Report was unsubmitted during this print-out.

< END OF ESTIMATES >