

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Ref:

PRE-REPAIR INSPECTION REPORT

8 SHENTON WAY #24-01 AXA TOWER

SINGAPORE 068811

AXA INSURANCE PTE LTD

10-11-2020 Date:

CS3/ASM20011969/Gtf3e2

Page No.:1 of 1

| Silve | JAI OILE 000011 | | | | |
|-------|------------------------|----------------------|-------------------------|-------------------------|--|
| ATT | N : KHOR SAW TE | NG | Code: ASM | | |
| 1. | | Policy Particulars | s :- (THIRD PARTY CLAIN | 1) | |
| | Insured Veh. | SGJ 1066T | Veh. Inspected | SMJ 8190A | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | S0M02WEE | Excess (\$) | 0.00 | |
| | Assign From | KHOR SAW TENG | Assign Date | 03/11/2020 | |
| 2. | | Vehicle Par | ticulars & Condition | | |
| | Make & Model | MERCEDES BENZ GLA180 | c.c | 1595 | |
| | Engine No. | HIDDEN | Year of Reg. | 2019 | |
| | Chassis No. | WDC1569422J589446 | Colour | RED | |
| | Odometer | 33227 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | | Cond | itions of Tyres | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 245/35Z R20 | YOKOHAMA | 6 mm | |
| | L/H Front Tyre | 245/35Z R20 | YOKOHAMA | 6 mm | |
| | R/H Rear Tyre | 245/35Z R20 | YOKOHAMA | 6 mm | |
| | L/H Rear Tyre | 245/35Z R20 | YOKOHAMA | 6 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SU | | | | |
| 5. | | Gene | ral Information | | |
| | Accident Date | 31/10/2020 | Inspect Date / Time | 03/11/2020 (12:00 PM) | |

| 5. | General Information | | | | | | |
|----|---------------------|--|---------------------|-------------------------|--|--|--|
| | Accident Date | 31/10/2020 | Inspect Date / Time | 03/11/2020 (12:00 PM) | | | |
| | Survey held at | KUM CHEW MOTOR WORKSHOP | | | | | |
| | | 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722 | | | | | |
| | | | | | | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

5b. **Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:

4 Working Days

Report Ref No. CS3/ASM20011969/Gtf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A **Automotive Assessor** BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.