

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011976/ESD3E2
Date: 15/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070130679
Claimant Vehicle No : SMD203G **Insured Vehicle No :** SLM5456A
Date of Loss: 31/10/2020 Nature of Claim: TP Claim No: 4780241507SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD203G**
Make & Model: NISSAN SYLPHY, 1.6 (A) Engine No: HR16926801C
Reg. Date: 30/07/2018 (Man. Year: 2018) Chassis No: MNTBBAB17Z0032168
Colour: Brown Odometer: 54235 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/11/2020
Date Inspected: 03/11/2020 Inspected At: 8 KAKI BUKIT AVE 4#04-20 PREMIER
Estimated Period of Repair: 2.0 days Repairer : A-tec Automotive Pte Ltd (KAKI BUKIT)

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT BUMPER	Broken	0.00 F	*- F	
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
3	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F	
4	1		*FRT LH BUMPER FOG LAMP COVER	Cut	0.00 F	*- F	
5	1		*FRT LH BUMPER FOG LAMP	* Check	0.00 F	*- F	
6	1		*FRT LH HEADLAMP ASSY	* Check	0.00 F	*- F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >