





| PRE-REPAIR INSPECTION REPORT                 |  |   |                         |   |
|--|--|---|-------------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD       |  | Ref: CS3/INC20011978/Eqf3e2   |                         |   |
| 73 BRAS BASAH ROAD                           |  | Date: 09-11-2020  |                         |   |
| #05-01 NTUC TRADE UNION HOUSESINGAPORE       |  |  |                         |   |
| 189556                                       |  |   |                         |   |
| ATTN: CHARLOTTE CHEW                         |  | Code: INC   |                         |   |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) |  |   |                         |   |
| Insured Veh.                                 | SJT 4874U  | Veh. Inspected  | FBQ 4832B               |   |
| Policy No.                                   |  | Coverage (\$)   | 0.00                    |   |
| Claim No.                                    | MT/1107914-001   | Excess (\$)   | 0.00                    |   |
| Assign From                                  | HAZALYSA BTE IBRAHIM   | Assign Date   | 03/11/2020              |   |
| 2. Vehicle Particulars & Condition           |  |   |                         |   |
| Make & Model                                 | YAMAHA MX KING   | c.c   | 150                     |   |
| Engine No.                                   | HIDDEN   | Year of Reg.  | 2019                    |   |
| Chassis No.                                  | MH3UG0750KK029778  | Colour  | BLUE                    |   |
| Odometer                                     | 25400 KM   | Steering  | IN ORDER                |   |
| Brakes                                       | IN ORDER   | Modification  | SPORTS RIM              |   |
| General                                      | GOOD   |   |                         |   |
| 3. Conditions of Tyres                       |  |   |                         |   |
|  | Size   | Make  | Balance                 |   |
| R/H Front Tyre                               | 70/80-17   | BRIDGESTONE   | 5 mm                    |   |
| L/H Front Tyre                               |  |   | mm                      |   |
| R/H Rear Tyre                                | 80/90-17   | BRIDGESTONE   | 5 mm                    |   |
| L/H Rear Tyre                                |  |   | mm                      |   |
| 4. Description of Damages                    |  |   |                         |   |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.   |   |                         |  |
| 5. General Information                       |  |   |                         |   |
| Accident Date                                | 23/10/2020   | Inspect Date / Time   | 03/11/2020 ( 01:26 PM ) |   |
| Survey held at                               | 149 KAKI BUKIT AVE 1 SOON LEE INDUSTRILA PARK  |   |                         |   |
| Repairer                                     | GARAGE 13 PTE LTD  |   |                         |   |
| 5a. Remarks                                  |  |   |                         |   |
|  | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |   |                         |   |

Report Ref No. CS3/INC20011978/Eqf3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.