

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20011980/KTF3Q2

**Date:** 10/04/2021

### REFERENCE

Insured/Claimant: FEDERAL EXPRESS (SINGAPORE) PTE LTD

Policy No: 0999993738

Date of Loss: 30/10/2020

Nature of Claim: OD Claim No: 2805616920SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ7174J**

Make & Model: MERCEDES-BENZ SPRINTER, 2.1 D 316 CDI (W906) (M) Engine No: 65195835043378

Reg. Date: 30/07/2019 (Man. Year: 2019) Chassis No: WDB9076332P092397

Colour: White Odometer: 17613 km

Engine Capacity: 2143 cc

Market Value/New Car Price: S\$76,000.00

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/65 R16 Rear Tyre Size: 235/65 R16

Front Left Side: Continental 9 mm Rear Left Side: Toyo 9 mm

Front Right Side: Continental 9 mm Rear Right Side: Toyo 9 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                | Repairer's       | Adjuster's       | Difference       | Diff %       |
|-------------------------------|------------------|------------------|------------------|--------------|
| Parts                         | 18,680.80        | 8,897.00         | 9,783.80         | 52.37        |
| Miscellaneous Items           | 0.00             | 0.00             | 0.00             |              |
| Labour                        | 2,340.00         | 1,500.00         | 840.00           | 35.90        |
| Paintwork Labour              | 0.00             | 0.00             | 0.00             |              |
| Towing                        | 0.00             | 0.00             | 0.00             |              |
| <b>Gross Total (S\$)</b>      | <b>21,020.80</b> | <b>10,397.00</b> | <b>10,623.80</b> | <b>50.54</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>1,471.46</b>  | <b>727.79</b>    | <b>743.67</b>    | <b>50.54</b> |
| <b>Nett Amount (S\$)</b>      | <b>22,492.26</b> | <b>11,124.79</b> | <b>11,367.47</b> | <b>50.54</b> |

### INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 03/11/2020 Inspected At:

Mega Auto Pte Ltd (HQ)  
160 Sin Ming Drive #02-01 AutoCity  
Singapore 575722

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

4/10/2021

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$5,098.70 NETT)

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition   | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------|-------------|-------------|--------------|
| 1   | 1   |          | *BONNET ASSY                     | Bent        | 1,145.00 FL | *1,145.00 FL |
| 2   | 1   |          | *BONNET HINGE RH                 | Repair      | 91.00 FL    | *- FL        |
| 3   | 1   |          | *BONNET HINGE LH                 | *Check      | 91.00 FL    | *- FL        |
| 4   | 1   |          | *BONNET LOCK                     | Repair      | 148.00 FL   | *- FL        |
| 5   | 1   |          | *BONNET CABLE                    | Serviceable | 54.00 FL    | *- FL        |
| 6   | 1   |          | *HEADLAMP LH                     | Mtg Cracked | 2,750.00 FL | *2,750.00 FL |
| 7   | 1   |          | *HEADLAMP RH                     | Serviceable | 2,750.00 FL | *- FL        |
| 8   | 1   |          | *FRONT GRILLE                    | Dented      | 980.00 FL   | *980.00 FL   |
| 9   | 1   |          | *FRONT BUMPER RETAINER RH        | Serviceable | 38.00 FL    | *- FL        |
| 10  | 1   |          | *FRONT BUMPER RETAINER LH        | Distorted   | 38.00 FL    | *38.00 FL    |
| 11  | 1   |          | *FRONT BUMPER                    | Dented      | 981.00 FL   | *981.00 FL   |
| 12  | 1   |          | *FRONT SUPPORT PANEL             | Cracked     | 360.00 FL   | *360.00 FL   |
| 13  | 1   |          | *FRONT BUMPER CENTRE GARNISH     | *Check      | 110.00 FL   | *- FL        |
| 14  | 1   |          | *SUPPORT PANEL GARNISH LH        | *Check      | 93.00 FL    | *- FL        |
| 15  | 1   |          | *SUPPORT PANEL CENTRE            | Cracked     | 65.00 FL    | *65.00 FL    |
| 16  | 10  |          | *FRONT FENDER INNER SHIELD CLIPS | Necessary   | 75.00 FL    | *75.00 FL    |
| 17  | 1   |          | *FRONT WINDSCREEN GLASS          | Cracked     | 2,200.00 FL | *2,200.00 FL |
| 18  | 1   |          | *RADIATOR ASSY                   | *Check      | 966.00 FL   | *- FL        |
| 19  | 1   |          | *RADIATOR FAN COWLING            | *Check      | 181.00 FL   | *- FL        |
| 20  | 1   |          | *RADIATOR FAN MOTOR              | *Check      | 499.00 FL   | *- FL        |
| 21  | 1   |          | *AIR CON MOTOR                   | Serviceable | 369.00 FL   | *- FL        |
| 22  | 1   |          | *A/C CONDENSER ASSY              | *Check      | 1,283.00 FL | *- FL        |
| 23  | 1   |          | *RADIATOR LOWER PIPE LH          | Serviceable | 153.00 FL   | *- FL        |
| 24  | 1   |          | *HORN                            | Dented      | 176.00 FL   | *176.00 FL   |
| 25  | 1   |          | *AIR FILTER BOX                  | Mtg Broken  | 420.00 FL   | *420.00 FL   |
| 26  | 1   |          | *AUTO OIL COOLER                 | *Check      | 971.00 FL   | *- FL        |
| 27  | 1   |          | *WIPER TANK                      | Serviceable | 112.00 FL   | *- FL        |
| 28  | 1   |          | *INTERCOOLER ASSY                | *Check      | 880.00 FL   | *- FL        |
| 29  | 1   |          | *AIRBAG CONTROL SWITCH           | Serviceable | 1,054.00 FL | *- FL        |
| 30  | 1   |          | *WHEEL HOUSE                     | Repair      | 550.00 FL   | *- FL        |
| 31  | 1   |          | *FRONT FENDER LH                 | Buckled     | 560.00 FL   | *560.00 FL   |
| 32  | 1   |          | *INTERCOOLER LOWER GARNISH       | *Check      | 49.00 FL    | *- FL        |
| 33  | 1   |          | *A/C FAN COWLING                 | Cracked     | 80.00 FL    | *80.00 FL    |
| 34  | 1   |          | *COOLANT 8L                      | Necessary   | 168.00 FS   | *50.00 FS    |
| 35  | 1   |          | *AUTO OIL 4L                     | *Check      | 108.00 FS   | *- FS        |
| 36  | 1   |          | *FEDEX DECAL                     | *Check      | 160.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>20,708.00</b> | <b>9,880.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 2,027.20         | 983.00          |
| <b>Total Parts (\$\$)</b>                                  | <b>18,680.80</b> | <b>8,897.00</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No                         | Qty | Particulars           | Repairer's | Amount |
|----------------------------|-----|-----------------------|------------|--------|
| <b>Miscellaneous Items</b> |     |                       |            |        |
| 1                          | 1   | *OD/TP Case (Insurer) | -          | 0.00   |
| Sub Total (S\$)            |     |                       | 0.00       | 0.00   |

Recommended Labour

| No                      | Particulars                                                                  | Lab.Type | Repairer's | Amount   |
|-------------------------|------------------------------------------------------------------------------|----------|------------|----------|
| <b>Labour Items</b>     |                                                                              |          |            |          |
| 1                       | TOP UP GAS.                                                                  | New      | 80.00      | 80.00    |
| 2                       | TOWING FEE.<br>(*Check)                                                      | New      | 180.00     | 0.00     |
| 3                       | R&R FRONT WINDSCREEN.                                                        | New      | 180.00     | 120.00   |
| 4                       | R&R RADIATOR, CONDENSER & INTERCOOLER.                                       | New      | 160.00     | 100.00   |
| 5                       | STRAIGHTEN & PANEL BEAT ACCIDENT AREA.                                       | New      | 800.00     | 600.00   |
| 6                       | RESPRAY BONNET, BONNET INNER, FRONT FENDER RH, FRONT FENDER LH, WHEEL HOUSE. | New      | 900.00     | 600.00   |
| 7                       | R&R BONNET STICKER.<br>(*Check)                                              | New      | 40.00      | 0.00     |
| Gross Labour Cost (S\$) |                                                                              |          | 2,340.00   | 1,500.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >