

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011981/QCD3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00092602001
Claimant Vehicle No :	SLH7995Z	Insured Vehicle No :	GZ3828P
Date of Loss:	30/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D204124/C02/GZ3828P/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH7995Z	Engine No:	LEB4263725
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71043804
Reg. Date:	18/11/2016 (Man. Year: 2016)	Odometer:	469391 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,740.24	3,957.04	5,783.20	59.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,100.00	700.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,540.24	5,057.04	6,483.20	56.18
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	11,540.24	4,050.00	7,490.24	64.91
+ GST 7.00/7.00% (S\$)	807.82	283.50	524.32	64.91
Nett Amount (S\$)	12,348.06	4,333.50	8,014.56	64.91

INSPECTION

Date of Assignment:	29/12/2020		
Date Inspected:	03/11/2020	Inspected At:	60 JALAN LAM HUAT# 04-35/36 CARROS CENTRE Repairer:Lcrf Pte Ltd (HQ)
Estimated Period of Repair:	3.0 days		

Adjuster: OI SUN PIN**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Mar 2021)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH7995Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crumpled	1,650.00 FL	*1,350.00 FL
2	1		*F/R FENDER	Dented	1,100.00 FL	*525.00 FL
3	1		*F/R FENDER INNER LINER	Cut	240.00 FL	*182.00 FL
4	1		*F/R FENDER HYBRID EMBLEM	Necessary	86.80 FL	*86.80 FL
5	1		*RADIATOR GRILLE CENTER MOULDING	Crumpled	390.00 FL	*248.00 FL
6	1		*RADIATOR GRILLE BASE	Crumpled	480.00 FL	*350.00 FL
7	1		*RADIATOR GRILLE LOWER MOULDING	Serviceable	330.00 FL	*- FL
8	1		*RADIATOR GRILLE EMBLEM	Necessary	48.00 FL	*48.00 FL
9	1		*F/L HEADLAMP	Serviceable	2,100.00 FL	*- FL
10	1		*F/R HEADLAMP	Crumpled	2,100.00 FL	*1,560.00 FL
11	1		*F/L HEADLAMP LOWER BRACKET	Serviceable	115.00 FL	*- FL
12	1		*F/R HEADLAMP LOWER BRACKET	Broken	115.00 FL	*115.00 FL
13	1		*FRONT BUMPER	Repeated	1,350.00 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Repair	660.00 FL	*- FL
15	1		*FRONT BUMPER RH TOW COVER	Serviceable	54.00 FL	*- FL
16	1		*FRONT BUMPER RH SIDE RETAINER	Broken	21.00 FL	*21.00 FL
17	1		*FRONT BUMPER LH SIDE RETAINER	Broken	21.00 FL	*21.00 FL
18	1		*FRONT BUMPER RH FOG LAMP COVER	Serviceable	150.00 FL	*- FL
19	1		*FRONT BUMPER LH FOG LAMP COVER	Serviceable	150.00 FL	*- FL
20	1		*FRONT BUMPER LOWER GRILLE	Serviceable	294.00 FL	*- FL
21	1		*SET BUMPER CLIPS	Necessary	120.00 FS	*30.00 FS
22	1		*SET FRONT NUMBER PLATE	Serviceable	80.00 FS	*- FS
23	1		*FRONT BUMPER UNDERDUST COVER	Crumpled	220.00 FL	*220.00 FL
24	1		*F/L FENDER INNER LINER	Cut	250.50 FL	*182.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,125.30	4,938.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,385.06	981.76

Total Parts (\$\$)	9,740.24	3,957.04
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE FRONT SUPPORT PANEL,FRONT BONNET,FRONT BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS ALSO INCDE CUTTING AND WELDING OF DAMAGED PARTS	New	900.00	500.00
2	TO RESPRAY FRONT BONNET,F/R FENDER,SUPPORT PANEL AND FRONT BUMPER (INNER/OUTER)	New	900.00	600.00
Gross Labour Cost (\$\$)			1,800.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >