

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011983/BGS3Q2
Date: 16/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800012992
Claimant Vehicle No :	SMQ8773G	Insured Vehicle No :	SJS1070Y
Date of Loss:	31/10/2020	Nature of Claim:	TP
		Claim No:	8532169806SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ8773G	Engine No:	L15B5574039
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11324011
Reg. Date:	06/12/2019 (Man. Year: 2019)	Odometer:	56386 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50R18	Rear Tyre Size:	225/50R18
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,878.08	14,392.96	12,485.12	46.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,950.00	3,820.00	3,130.00	45.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,828.08	18,212.96	15,615.12	46.16
+ GST 7.00/7.00% (S\$)	2,367.97	1,274.91	1,093.06	46.16

Nett Amount (S\$)	36,196.05	19,487.87	16,708.18	46.16
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (11.0 x S\$100.00/day) (S\$)		1,100.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		109.20		
Nett Liability (S\$)		21,033.52		

INSPECTION

Date of Assignment:	03/11/2020		
Date Inspected:	04/11/2020	Inspected At:	160 SIN MING DR #01-14
Estimated Period of Repair:	12.0 days		Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,050.00 FL	*817.90 FL
2	1		*FRONT BUMPER LOWER	Broken	485.60 FL	*458.30 FL
3	2		*FRONT BUMPER SIDE RETAINER	Necessary	144.00 FL	*130.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Broken	486.00 FL	*321.70 FL
5	2		*FRONT BUMPER FOG LAMP	Broken	913.40 FL	*890.00 FL
6	2		*FRONT BUMPER FOG LAMP GARNISH	Cut	252.40 FL	*210.00 FL
7	1		*FRONT BUMPER GRILLE	Broken	582.30 FL	*440.50 FL
8	1		*FRONT BUMPER GRILLE LOGO	Necessary	89.00 FL	*38.80 FL
9	1		*FRONT BUMPER GRILLE BASE	No such part	413.60 FL	*- FL
10	1		*FRONT BUMPER GRILLE OUTER CHROME GARNISH	Broken	368.00 FL	*368.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Broken	198.60 FL	*123.70 FL
12	2		*FRONT BUMPER GRILLE TOP BRACKET SIDE	Broken	174.60 FL	*91.60 FL
13	1		*FRONT BUMPER GRILLE TOP BRACKET CENTRE	Broken	198.00 FL	*38.70 FL
14	1		*FRONT BUMPER TOW CAP	Missing	83.20 FL	*46.80 FL
15	1		*FRONT LICENSE PLATE	Broken	98.00 FL	*50.00 FL
16	2		*HEADLAMP ASSY	Broken	4,291.80 FL	*3,847.00 FL
17	2		*HEADLAMP BRACKET	Broken	152.00 FL	*70.00 FL
18	1		*BONNET	Dented	1,034.70 FL	*1,034.70 FL
19	1		*BONNET LOCK ASSY	Bent	234.60 FL	*109.50 FL
20	1		*BONNET INSULATOR	Broken	396.40 FL	*211.30 FL
21	2		*BONNET HINGE	Bent	178.00 FL	*178.00 FL
22	2		*BONNET RUBBER (SHORT)	Necessary	182.00 FL	*75.00 FL
23	1		*BONNET RUBBER (LONG)	Necessary	135.00 FL	*135.00 FL
24	1		*FRONT SUPPORT PANEL	Dented	898.00 FL	*576.20 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	185.00 FL	*185.00 FL
26	2		*FRONT SUPPORT PANEL SIDE GARNISH	Not Damaged	169.20 FL	*- FL
27	1		*FRONT FENDER	N/S Dented	1,512.00 FL	*756.00 FL
28	2		*FRONT FENDER INNER COWLING	Torn	268.40 FL	*130.00 FL
29	2		*FRONT FENDER ARCH GARNISH	Broken	257.80 FL	*257.80 FL
30	2		*FRONT DOOR	Repair	2,560.00 FL	*- FL
31	2		*FRONT DOOR BLACK TAPE	Not Necessary	136.00 FL	*- FL
32	1		*FRONT WIPER WASHER TANK	Broken	265.80 FL	*265.80 FL
33	1		*FRONT WIPER WASHER TANK MOTOR	Not Damaged	150.00 FL	*- FL
34	1		*FRONT WIPER GARNISH	Not Damaged	425.60 FL	*- FL
35	1		*RADIATOR	Bent	987.90 FL	*987.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*RADIATOR FAN MOTOR	Not Damaged	1,076.00 FL	*- FL
37	2		*RADIATOR FAN COWLING	Broken	431.20 FL	*350.00 FL
38	2		*RADIATOR FAN BLADE	Not Damaged	232.00 FL	*- FL
39	1		*RADIATOR TOP HOSE	Not Damaged	148.60 FL	*- FL
40	1		*RADIATOR LOWER HOSE	Not Damaged	159.30 FL	*- FL
41	1		*FAN BELT	Not Damaged	194.50 FL	*- FL
42	1		*AIRCON COMPRESSER	Not Damaged	853.20 FL	*- FL
43	1		*AIRCON COMPRESSER BELT	Not Necessary	354.00 FL	*- FL
44	1		*AIRCON CONDENSER	Broken	985.00 FL	*788.00 FL
45	1		*AIRCON SUCTION HOSE	Bent	398.00 FL	*198.00 FL
46	1		*AIRCON DISCHARGE HOSE	Bent	352.00 FL	*275.00 FL
47	1		*AIR DUCT	Not Damaged	86.90 FL	*- FL
48	1		*AIR CLEANER BOX	Not Damaged	482.10 FL	*- FL
49	1		*FRONT CHASSIS MEMBER	Bent	1,985.60 FL	*1,510.00 FL
50	1		*ALTERNATOR ASSY	Not Damaged	985.20 FL	*- FL
51	1		*STARTER MOTOR ASSY	Not Damaged	954.60 FL	*- FL
52	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
53	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
54	1		*FRONT BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS
55	2		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Necessary	100.00 FS	*30.00 FS
56	1		*FRONT BUMPER GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
57	1		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
58	1		*BONNET SEALANT	Necessary	100.00 FS	*40.00 FS
59	1		*BONNET INSULATOR CLIPS	Necessary	50.00 FS	*30.00 FS
60	1		*BONNET RUBBER CLIPS	Necessary	150.00 FS	*60.00 FS
61	1		*BONNET AIR DUCT	Not Necessary	250.00 FS	*- FS
62	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
63	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
64	2		*FRONT SUPPORT PANEL SIDE GARNISH CLIPS	Necessary	100.00 FS	*40.00 FS
65	1		*FRONT FENDER SEALANT	N/S Necessary	200.00 FS	*60.00 FS
66	2		*FRONT FENDER INNER COWLING CLIPS	Necessary	100.00 FS	*60.00 FS
67	2		*FRONT FENDER ARCH GARNISH CLIPS	Necessary	100.00 FS	*60.00 FS
68	2		*FRONT DOOR SEALANT	Not Necessary	200.00 FS	*- FS
69	1		*FRONT WIPER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
70	1		*HORN	Not Damaged	80.00 FS	*- FS
71	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
72	1		*AIRCON FLUID	Necessary	80.00 FS	*40.00 FS
73	1		*BRAKE FLUID	Not Necessary	80.00 FS	*- FS
74	1		*NUMBER PLATE WITH CASING	Broken	80.00 FS	*50.00 FS
75	2		*HEADLAMP OUTER CHROME GARNISH	Missing	220.00 FL	*220.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
76	1		*INTAKE MANIFOLD	Cut	880.00 FL	*880.00 FL	
77	1		*INTAKE MANIFOLD GASKET	Necessary	60.00 FS	*60.00 FS	
					Sub Total (\$)	33,025.10	17,806.20
					- List Item Discount on L Items 20.00/20.00% (\$)	6,147.02	3,413.24
					Total Parts (\$)	26,878.08	14,392.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BONNET COMPONENT	New	150.00	60.00
2	R&R WIPER GARNISH	New	150.00	50.00
3	R&R ABS PUMP	New	250.00	0.00
4	CHECK WIRING	New	100.00	40.00
5	R&R RADIATOR	New	150.00	70.00
6	R&R CONDENSER	New	150.00	70.00
7	R&R AIRCON COMPRESSER	New	150.00	0.00
8	R&R ALTERNATOR ASSY	New	150.00	50.00
9	R&R STARTER MOTOR ASSY	New	150.00	0.00
10	DIAGNOSTIC AND RESET FAULT CODE	New	300.00	120.00
11	UPHOLSTERY	New	300.00	0.00
12	MOUNT WORK BENCH	New	300.00	0.00
13	CHASIS ALIGNMENT	New	300.00	200.00
14	PANEL BEATING	New	2,000.00	1,600.00
15	RUST PROOFING	New	200.00	80.00
16	SPRAY PAINTING	New	2,000.00	1,400.00
17	R&R INTAKE MANIFOLD	New	150.00	80.00
Gross Labour Cost (S\$)			6,950.00	3,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >