

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011984/AGA3Q2

Date: 27/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100435286

Claimant
Vehicle No : FBN8872A **Insured Vehicle No :** SKZ5688R

Date of Loss: 01/11/2020 Nature of Claim: TP Claim No: 7687025104SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN8872A		
Make & Model:	YAMAHA MX KING T150, 150cc	Engine No:	G3E6E0433703
Reg. Date:	31/12/2018 (Man. Year: 2018)	Chassis No:	MH3UG0710JK276125
Colour:	Black	Odometer:	24649 km
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/80R17	Rear Tyre Size:	120/70R17
Front Left Side:	IRC 6 mm	Rear Left Side:	IRC 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,757.00	2,465.00	1,292.00	34.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	580.00	320.00	35.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,657.00	3,045.00	1,612.00	34.61
Approved Total (Overridden) (\$\$)		2,400.00		
Nett Amount (\$\$)	4,657.00	2,400.00	2,257.00	48.46
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 03/11/2020 Inspected At:

Automobile Hub Enterprise
1 KAKI BUKIT AVENUE 5, #2 -11
AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	75.00 FL	*75.00 FL
2	1		*FRONT WHEEL SHAFT	Bent	45.00 FL	*45.00 FL
3	1		*FRONT FORK ASSY	Bent	480.00 FL	*480.00 FL
4	1		*FRONT FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
5	1		*STEERING CONE AND BEARING	Necessary	65.00 FL	*65.00 FL
6	1		*FRONT COWLING	Cracked	165.00 FL	*165.00 FL
7	1		*FRONT COWLING BASE	Cracked	155.00 FL	*155.00 FL
8	1		*FRONT LH SIGNAL LAMP	Not Necessary	45.00 FL	*- FL
9	1		*HEADLAMP	Not Necessary	185.00 FL	*- FL
10	1		*HEADLAMP COVER	Not Necessary	55.00 FL	*- FL
11	2		*FRONT FAIRING SIDE (SILVER)	Cracked	370.00 FL	*370.00 FL
12	2		*YAMAHA LOGO	Necessary	40.00 FL	*40.00 FL
13	1		*BALANCER LH	Cut	35.00 FL	*35.00 FL
14	1		*HANDLE BAR	Not Necessary	135.00 FL	*- FL
15	1		*FRONT LH WING MIRROR	Cut	40.00 FL	*40.00 FL
16	1		*BRAKE LEVER	Cut	30.00 FL	*30.00 FL
17	1		*FOOT BRAKE LEVER	Bent	55.00 FL	*55.00 FL
18	1		*FOOT BRAKE LEVER RUBBER	Cut	20.00 FL	*20.00 FL
19	1		*FRONT FOOTREST BRACKET	Bent	145.00 FL	*145.00 FL
20	1		*ENGINE COVER	Cut	390.00 FL	*320.00 FL
21	1		*REAR LH FOOTREST	Not Necessary	20.00 FL	*- FL
22	1		*REAR LH FOOTREST BRACKET	Cut	75.00 FL	*75.00 FL
23	1		*REAR LH SIDE FAIRING	Not Necessary	190.00 FL	*- FL
24	1		*SWING ARM	Not Necessary	380.00 FL	*- FL
25	1		*FRONT WHEEL RIM	Cut	380.00 FS	*200.00 FS
26	1		*FRONT TYRE	Not Necessary	140.00 FS	*- FS
27	1		*BOT FORK OIL	Necessary	40.00 FS	*40.00 FS
28	1		*SET FORK OIL SEAL	Necessary	55.00 FS	*55.00 FS
29	1		*SET STICKERS	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,095.00	2,695.00
- List Item Discount on L Items 10.00/10.00% (S\$)	338.00	230.00
Total Parts (S\$)	3,757.00	2,465.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVE AND REFIT PARTS	New	400.00	250.00
2	SPRAY PAINTING TO AFFECTED AREA	New	400.00	250.00
3	WIRING CHECK	New	50.00	30.00
4	TOWING FEES	New	50.00	50.00
Gross Labour Cost (\$\$)			900.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >