

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011985/UTF3E2
Date: 18/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN00002432003	
Claimant Vehicle No : SLZ1960T	Insured Vehicle No : SGQ4318K	
Date of Loss: 02/11/2020	Nature of Claim: TP	Claim No: SNM20D204162/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLZ1960T		
Make & Model: HYUNDAI ELANTRA, 1.6 (A)	Engine No: G4FGJU151024	
Reg. Date: 26/04/2018 (Man. Year: 2018)	Chassis No: KMHD841CMJU646950	
Colour: Beige	Odometer: 84912 km	
Engine Capacity: 1591 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15	Rear Tyre Size: 195/65R15	
Front Left Side: Goodyear 6 mm	Rear Left Side: Goodyear 6 mm	
Front Right Side: Goodyear 6 mm	Rear Right Side: Goodyear 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,448.40	867.60	580.80	40.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	620.00	510.00	45.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,578.40	1,487.60	1,090.80	42.31
+ GST 7.00/7.00% (S\$)	180.49	104.13	76.36	42.31
Nett Amount (S\$)	2,758.89	1,591.73	1,167.16	42.31

INSPECTION

Date of Assignment: 04/11/2020		
Date Inspected: 09/11/2020	Inspected At:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair: 3.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2020)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ1960T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	459.40 FL	*459.40 FL
2	2		*REAR BUMPER RETAINER	Not Necessary	88.60 FL	*- FL
3	10		*FRT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	1		*REAR BUMPER SPOILER	Grazed	605.00 FL	*280.10 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	295.00 FL	*295.00 FL
6	1		*REVERSE SENSOR	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,748.00	1,084.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	299.60	216.90
Total Parts (\$\$)	1,448.40	867.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	30.00	20.00
2	LABOUR CHARGE	New	500.00	200.00
3	SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (S\$)			1,130.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >