Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011989/QRA3Q2

Date: 12/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900236608

Claimant
Vehicle No: SLM725G Insured Vehicle No: SMQ3550R

Date of Loss: 28/10/2020 Nature of Claim: TP Claim No: 3593763955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM725G

 Make & Model:
 TOYOTA SIENTA HYBRID, 1.5 X CVT (A)
 Engine No:
 1NZR456763

 Reg. Date:
 20/03/2017 (Man. Year: 2016)
 Chassis No:
 NHP1707066342

 Colour:
 Blue
 Odometer:
 354306 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Gremax 6 mm Rear Left Side: Gremax 6 mm
Front Right Side: Gremax 6 mm
Rear Right Side: Gremax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,055.25	778.75	5,276.50	87.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	760.00	1,560.00	67.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,375.25	1,538.75	6,836.50	81.63
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	8,375.25	1,250.00	7,125.25	85.08
+ GST 7.00/7.00% (S\$)	586.27	87.50	498.77	85.08
Nett Amount (S\$)	8,961.52	1,337.50	7,624.02	85.08
Global Sum S	settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 03/11/2020 Inspected At: Lion City Rentals Pte Ltd (HQ)

60 Jalan Lam Huat, #04-35/36 Carros

Centre

Singapore 737569

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: Jaslin Kok Chin Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*F/R FENDER	Repair	924.00 FL	*-FL	
2	1		*F/R FENDER INNER LINER	Serviceable	234.00 FL	*-FL	
3	1		*F/R STRUT ASSY	Serviceable	580.20 FL	*-FL	
4	1		*F/R STRUT MOUNTING	Serviceable	120.50 FL	*-FL	
5	1		*F/R LOWER ARM	Bent	520.30 FL	*325.00 FL	
6	1		*F/R STEERING KNUCKLE	Serviceable	480.00 FL	*-FL	
7	1		*F/R STABILIZER LINK	Serviceable	448.00 FL	*-FL	
8	1		*STEERING RACK & PINION ASSY	Serviceable	3,800.00 FL	*-FL	
9	1		*F/R WHEEL HUB BEARING	Jammed	220.00 FL	*220.00 FL	
10	1		*SET BUMPER CLIPS	Serviceable	80.00 FS	*-FS	
11	1		*SET F/R WHEEL COVER	Crushed	180.00 FS	*120.00 FS	
12	1		*F/R WHEEL RIM	Bent	300.00FS	*250.00 FS	
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.				
				Sub Total (S\$)	7,887.00	915.00	
			- List Item Discount on L Items 25	.00/25.00% (S\$) _	1,831.75	136.25	
				Total Parts (S\$)	6,055.25	778.75	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO LABOUR CHARGE FOR REMOVING FRONT BUMPERAND F/R FENDER OUT TO FACILITATE REPLACEMENT OF PARTS	New	900.00	250.00
2	TO RESPRAY FRONT BUMPER AND F/R FENDER	New	900.00	200.00
3	TO REMOVE F/R SUSPENSION PARTS OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	New	400.00	250.00
4	TO CONDUCT 4 POST WHEEL ALIGNMENT	New	120.00	60.00
	Gross Lab	Gross Labour Cost (S\$)		760.00
	Report was unsubmitted du	rring this print-out.		

< END OF ESTIMATES >