

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20011994/KBA3Q2

**Date:** 15/03/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700086921

**Claimant**  
**Vehicle No :** SLP891T **Insured Vehicle No :** GBG9749D

Date of Loss: 28/10/2020 Nature of Claim: TP Claim No: 9027019462SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP891T		
Make & Model:	TOYOTA NOAH, 2.0 X (A)	Engine No:	3ZRB932606
Reg. Date:	25/05/2017 (Man. Year: 2016)	Chassis No:	ZRR800266014
Colour:	Metallic Silver	Odometer:	81337 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,466.83	4,256.83	210.00	4.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	970.00	670.00	40.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>6,106.83</b>	<b>5,226.83</b>	<b>880.00</b>	<b>14.41</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	427.48	365.88	61.60	14.41
<b>Nett Amount (\$\$)</b>	<b>6,534.31</b>	<b>5,592.71</b>	<b>941.60</b>	<b>14.41</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>5,894.71</b>		

### INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 04/11/2020 Inspected At:

Ah Lim Motor Company (AMK)  
10 Ang Mo Kio Industrial Park 2A,  
#01-09 AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	620.00 FL	*620.00 FL
2	20		*FRONT BUMPER CLIPS	Necessary	80.00 FL	*80.00 FL
3	1		*HEADLAMP RH	Cracked	3,355.00 FL	*3,355.00 FL
4	1		*FOGLAMP COVER RH	Mtg Distorted	227.00 FL	*227.00 FL
5	1		*FOGLAMP RH	Serviceable	280.00 FL	* - FL
6	1		*FRONT PARKING SENSOR	Shorted	200.00 FS	*200.00 FS
7	1		*FRONT GRILLE	Cracked	935.30 FL	*935.30 FL
8	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	191.81 FL	*191.81 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,889.11</b>	<b>5,609.11</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,422.28	1,352.28
<b>Total Parts (\$)</b>	<b>4,466.83</b>	<b>4,256.83</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING WIRE ,SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	30.00	20.00
2	TO DISMANTLE ALL DAMAGED PARTS ,TO CUT & WELD ,TO KNOCK & REPAIR FRONT FENDER INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	400.00	300.00
3	TO SPRAY FRONT BUMPER ,FRONT FENDER	New	500.00	400.00
4	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
5	TO REPAIR FRONT SUPPORT PANEL AND FENDER LH	New	200.00	0.00
6	TO SPRAY BONNET ,FRONT SUPPORT PANEL AND FENDER LH	New	450.00	200.00
<b>Gross Labour Cost (\$)</b>			<b>1,640.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >