

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011996/ESD3E2

Date: 15/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100467555
Claimant Vehicle No : XD4475G **Insured Vehicle No :** SDK6168E
Date of Loss: 28/10/2020 Nature of Claim: TP Claim No: 0538307605SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD4475G**
Make & Model: SCANIA P380CA4X2MSZ, 11.7 D (M) Engine No: 6617653
Reg. Date: 11/01/2011 (Man. Year: 2010) Chassis No: XLEP4X20005237724
Colour: Multi-colour Odometer: 493818 km
Engine Capacity: 11705 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5
Front Left Side: FRONWAY 5 mm Rear Left Side: FRONWAY 5 mm
Front Right Side: FRONWAY 5 mm Rear Right Side: FRONWAY 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/11/2020
Date Inspected: 23/11/2020 Inspected At: M.s Panel Beating Workshop (HQ)
2 KAKI BUKIT AVENUE 2
#02-17 KAKI BUKIT AUTOHUB
SINGAPORE 417921
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER (LH)	Broken	0.00 F	*- F
2	1		*FRT SIGNAL LAMP LH	Broken	0.00 F	*- F
3	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
4	1		*FRT STEP (LH)	Broken	0.00 F	*- F
5	1		*FRT STEP PANEL GARNISH	Broken	0.00 F	*- F
					Total Parts (S\$)	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >