

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20011997/UBA3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : GBG908X	Insured Vehicle No :	SHC8094R
Date of Loss: 27/10/2020	Nature of Claim: TP	Claim No: MCT20100450

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG908X		
Make & Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)	Engine No:	K9KC400D056517
Reg. Date:	31/05/2017 (Man. Year: 2016)	Chassis No:	VSKYBAM20Z0141072
Colour:	Blue/Silver	Odometer:	114770 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	ULTIMA-X 6 mm	Rear Left Side:	ULTIMA-X 6 mm
Front Right Side:	ULTIMA-X 6 mm	Rear Right Side:	ULTIMA-X 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,844.40	2,570.44	3,273.96	56.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,860.00	1,220.00	1,640.00	57.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,704.40	3,790.44	4,913.96	56.45
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	8,704.40	3,000.00	5,704.40	65.53
+ GST 7.00/7.00% (S\$)	609.31	210.00	399.31	65.53
Nett Amount (S\$)	9,313.71	3,210.00	6,103.71	65.53
+ Car Rental (4.0 x S\$130.00/day + 7.00% GST) (S\$)		556.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,773.85		
Global Sum Settlement (S\$)		3,750.00		

INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 10/11/2020 Inspected At:

Abwin Service Pte Ltd - 17 Kaki Bukit (HQ)
No.17 Kaki Bukit Road 4, #01-60

Bartley Biz Centre
Singapore 417809

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Dec 2020)	
Parts:	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG908X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	688.00 F	*600.50 FN
2	1		*REAR BUMPER RETAINER LH	Bent	45.00 F	*30.00 FN
3	1		*TAIL LAMP LH	Not Necessary	236.50 F	*- FN
4	1		*REAR END PANEL	Repair	248.00 F	*- FN
5	1		*REAR DOOR LH	Badly Dented	1,404.90 F	*1,281.10 FN
6	1		*REAR DOOR HINGE LOWER LH	Not Necessary	152.00 F	*- FN
7	1		*REAR FENDER LH	Repair	1,840.00 F	*- FN
8	1		*ADVERTISEMENT STICKER (REAR)	Necessary	800.00 FS	*600.00 FS
9	1		*SET REAR BUMPER SENSOR	Shorted	380.00 FS	*200.00 FS
10	1		*SET BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	5,844.40	2,761.60
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	191.16
Total Parts (\$\$)	5,844.40	2,570.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	1,000.00	550.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	600.00
3	TO DISMANTLE ,REPLACE AND /OR REPAIR CAMERA & TRSTING }	New	380.00	50.00
4	TO DISMANTLE ,REPLACE AND /OR REPAIR REVERSE SENSOR & TESTING }	New	180.00	0.00
5	TO CHECK WIRING	New	100.00	20.00
Gross Labour Cost (\$\$)			2,860.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >