LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG20011999/T1TF3E2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 03/06/2021

REFERENCE

Insured/Claimant: WONG CHEE WENG Policy No: 2100400305

Date of Loss: 30/10/2020 Nature of Claim: OD Claim No: 1292151103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCU1680J

Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CZC209954

Reg. Date: 26/01/2015 (Man. Year: 2014) Chassis No: WAUZZZ8V2F1044146

Colour: Grey Odometer: 107321 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$52,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		16,255.00	7,152.00	9,103.00	56.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		9,712.00	5,932.00	3,780.00	38.92
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	25,967.00	13,084.00	12,883.00	49.61
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	25,367.00	12,484.00	12,883.00	50.79
	+ GST 7.00/7.00% (S\$)	1,775.69	873.88	901.81	50.79
	Nett Amount (S\$)	27,142.69	13,357.88	13,784.81	50.79

INSPECTION

Date of Assignment: 03/11/2020

Date Inspected: 03/11/2020 Inspected At: 24 BENOI SECTOR Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,847.00 FS *1,477.60 FS	
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*-FS
3	1		*REAR BUMPER GUIDE SECTION - LH / RH	N/S Cracked /O/S Not Necessary	32.00 FS	*25.12 FS
4	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	59.00 FS	*-FS
5	1		*REAR BUMPER SPOILER	Deformed	234.00 FS	*187.20 FS
6	2		*REAR LIGHT REFLECTOR - LH / RH	Not Necessary	82.00 FS	*-FS
7	2		*LED LICENSE PLATE LIGHT	Not Necessary	113.00 FS	*- FS
8	1		*LED TAIL LIGHT - LH / RH INNER	N/S Cut / O/S NotNecessary	1,734.00 FS	*693.60 FS
9	1		*TAIL LIGHT TRIM - LH / RH INNER	N/S Deformed/ O/S NotNecessary	60.00 FS	*23.36 FS
10	2		*LED TAIL LIGHT - LH / RH OUTER	Not Necessary	1,734.00 FS	*-FS
11	2		*TAIL LIGHT TRIM - LH / RH OUTER	Not Necessary	60.00 FS	*- FS
12	1		*REAR REINFORCEMENT BEAM	Bent	565.00 FS	*451.60 FS
13	2		*REAR BUMPER BRACKET - LH / RH	Bent	26.00 FS	*19.84 FS
14	1		*REAR PARKING AID SENSOR - INNER / OUTER (2PCS)	Not Working (1Pc Only)	484.00 FS	*193.04 FS
15	4		*REAR PARKING AID SEAL RING	Necessary	14.00 FS	*10.88 FS
16	1		*SET REAR BUMPER WIRING	Not Necessary	510.00 FS	*- FS
17	1		*REAR LID	Bent	2,564.00 FS	*2,051.20 FS
18	1		*REAR LID ATTACHMENT PARTS	Not Necessary	291.00 FS	*- FS
19	2		*REAR LID HINGE - LH / RH	Not Necessary	506.00 FS	*- FS
20	1		*REAR LID FLAP GASKET	Not Necessary	203.00 FS	*- FS
21	1		*REAR LID LOCK STRIKER	Bent	49.00 FS	*39.20 FS
22	1		*REAR LID LOCK	Not Necessary	184.00 FS	*-FS
23	1		*REAR LID PUSH BUTTON	Not Necessary	172.00 FS	*- FS
24	1		*REAR LID COVER	Not Necessary	16.00 FS	*-FS
25	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.40 FS
26	1		*AUDI EMBLEM	Necessary	122.00 FS	*97.60 FS
27	1		*A3 INSCRIPTION	Necessary	95.00 FS	*75.36 FS
28	1		*TFSI INSCRIPTION	Necessary	95.00 FS	*75.36 FS
29	1		*REAR CROSS PANEL	Bent	356.00 FS	*284.40 FS
30	1		*CROSS PANEL REINFORCEMENT	Bent	725.00 FS	*579.60 FS
31	2		*CROSS PANEL CONNECTING PLATE - LH / RH	Bent	286.00 FS	*228.00 FS
32	1		*REAR CROSS PANEL TRIM	Deformed	153.00 FS	*122.40 FS
33	1		*LUGGAGE COMPARTMENT FLOORING	Not Necessary	536.00 FS	*- FS
34	1		*REAR LID TRIM PANEL	Not Necessary	303.00 FS	*- FS
35	1		*REAR SILENCER	Not Necessary	712.00 FS	*- FS
36	1		*REAR SILENCER DUAL CLIP	Not Necessary	57.00 FS	*- FS
37	2		*EXHAUST SYSTEM RETAINER	Not Necessary	79.00 FS	*- FS
38	1		*EXHAUST TAIL PIPE TRIM - LH	Not Necessary	128.00 FS	*- FS
39	1		*REAR BUMPER LOWER SPOILER CHROME TRIM (NPA)	Bent	0.00 FS	*- FS
40	1		*REAR NO PLATE	Not Necessary	60.00 FS	*-FS
41	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
42	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
43	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
44	1		*SUNDRIES	Necessary	300.00 FS	*2.24 FS
F=Fra	nchise	part. S=S		•		

Total Parts (S\$) 16,255.00 7,152.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	480.00	480.00
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	2,500.00
5	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING	New	3,800.00	2,200.00
6	TO RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour	r Cost (S\$)	9,712.00	5,932.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >