

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012005/RISD3Q2

Date: 25/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00005792000
Claimant Vehicle No :	GBB333E	Insured Vehicle No :	SLT8381A
Date of Loss:	16/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D203913C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB333E	Engine No:	AXE060996
Make & Model:	VOLKSWAGEN T5-SHUTTLE, 2.5 D (A)	Chassis No:	WV2ZZZ7HZ6X027456
Reg. Date:	30/09/2006 (Man. Year: 2006)	Odometer:	48697 km
Colour:	Black		
Engine Capacity:	2461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R16	Rear Tyre Size:	215/65R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,280.00	0.00	3,280.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	900.00	1,480.00	62.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,660.00	900.00	4,760.00	84.10
+ GST 7.00/7.00% (S\$)	396.20	63.00	333.20	84.10
Nett Amount (S\$)	6,056.20	963.00	5,093.20	84.10

INSPECTION

Date of Assignment:	03/11/2020	
Date Inspected:	04/11/2020 Inspected At:	Motorway Car Care Centre Pte Ltd (HQ)
		1094 Lower Delta Road, Motorway Building
		Singapore 169205
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Nov 2020)	
Parts:	N/A	VOLKSWAGEN T5-SHUTTLE 2.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB333E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	950.00 FL	*- FL
2	1		*REAR FENDER LH	Repair	2,650.00 FL	*- FL
3	1		*REAR BUMPER CLIPS	Not Necessary	40.00 FS	*- FS
					Sub Total (\$\$)	0.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	0.00
					Total Parts (\$\$)	0.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	1,000.00	400.00
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	1,200.00	500.00
3	TO APPLY ANTI RUST TREATMENT ON THE REPLACED AND REPAIRED PANELS	New	180.00	0.00
Gross Labour Cost (\$\$)			2,380.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >