

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20012015/KGS3Q2

Date:

12/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100504609

Claimant Vehicle No : SKK6394K**Insured Vehicle No :**

SFR8003Z

Date of Loss: 02/11/2020

Nature of Claim:

TP

Claim No:

6688216631SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKK6394K**

Make & Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZR1273066

Reg. Date: 14/08/2013 (Man. Year: 2013)

Chassis No: JTDGG20W705003832

Colour: Metallic Gold

Odometer: 240341 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Arivo 9 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Arivo 9 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,403.28	5,732.95	1,670.33	22.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	2,680.00	890.00	24.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,973.28	8,412.95	2,560.33	23.33
Approved Total (Overridden) (S\$)		6,700.00		

(S\$)	10,973.28	6,700.00	4,273.28	38.94
+ GST 7.00/7.00% (S\$)	768.13	469.00	299.13	38.94
Nett Amount (S\$)	11,741.41	7,169.00	4,572.41	38.94
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		7,897.00		

INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 04/11/2020

Estimated Period of Repair: 7.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	543.90 FL	*543.90 FL
2	1		*REAR BUMPER BRACKETS	N/S Repair / O/S Dented	111.00 FL	*55.50 FL
3	1		*REAR BUMPER RH SIDE RETAINER	Distorted	89.90 FL	*89.90 FL
4	1		*REAR BUMPER RH REFLECTOR	Serviceable	56.90 FL	*- FL
5	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
6	1		*REAR TAILGATE	Bent	1,275.90 FL	*1,275.90 FL
7	1		*TAILGATE LOGO	Necessary	66.15 FL	*66.15 FL
8	1		*TAILGATE OUTER MOULDING	Cracked	309.70 FL	*309.70 FL
9	1		*TAILGATE INNER LOCK	Dented	361.60 FL	*361.60 FL
10	1		*TAILGATE INNER RUBBER (50%)	Dented / Distorted	226.95 FS	*151.30 FS
11	1		*TAILGATE RH REFLECTOR	Cracked	349.20 FL	*349.20 FL
12	1		*TAILGATE EMBLEM(VALUE)	Necessary	39.90 FL	*39.90 FL
13	1		*TAILGATE INNER BOARD	Mtg Cracked	382.10 FL	*382.10 FL
14	1		*REAR WINDSCREE GLASS MOULDING	Necessary	129.80 FL	*129.80 FL
15	1		*RH TAILLAMP	Cracked	379.20 FL	*379.20 FL
16	1		*RH TAILLAMP LOWER RETAINER	Distorted	49.90 FL	*49.90 FL
17	1		*REAR END PANEL OUTER	Bent	495.90 FL	*495.90 FL
18	1		*REAR END PANEL INNER	Repair	199.20 FL	*- FL
19	1		*REAR END PANEL INNER TOP GARNISH	Buckled	253.29 FL	*253.29 FL
20	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	14.00 FL	*14.00 FL
21	1		*REAR FLOORBOARD TOP BOARD	Dented	569.20 FL	*569.20 FL
22	1		*REAR FLOORBOARD TOP BOARD SUPPORT	Cracked	359.80 FL	*359.80 FL
23	1		*REAR RH FENDER INNER GARNISH	Cracked	721.30 FL	*721.30 FL
24	1		*REAR RH FENDER	Repair	911.40 FL	*- FL
25	1		*REAR RH FENDER GLASS MOULDING	Not Necessary	369.90 FL	*- FL
26	1		*TAILGATE EMBLEM (ELEGANCE)	Necessary	50.00 FS	*50.00 FS
27	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
28	1		*REAR RH FENDER GLASS GUM	Not Necessary	20.00 FS	*- FS
29	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
30	1		*REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS
31	1		*REVERSE CAMERA	Serviceable	380.00 FS	*- FS
32	1		*REAR SMART KEY SENSOR	Cracked	144.20 FL	*144.20 FL
33	1		*SEPERATOR ROOM BOX	Cracked	384.10 FL	*384.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)**9,550.39****7,481.84**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					2,147.11	1,748.89
Total Parts (S\$)					7,403.28	5,732.95
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX SEAT ,CARPET ,GARNISH ,TOP ROOF LINING ,ETC	New	120.00	120.00
3	REMOVE & REFIX REAR RH FENDER GLASS	New	80.00	0.00
4	PANEL BEATING	New	1,800.00	1,100.00
5	PUTTY & RESPRAY PAINT	New	1,300.00	1,200.00
6	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	50.00	50.00
7	RUSTPROOFING	New	100.00	90.00
Gross Labour Cost (S\$)			3,570.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >