

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012017/DPS3Q2
Date: 30/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070088058
Claimant Vehicle No :	SLQ4696J	Insured Vehicle No :	GBB8681Y
Date of Loss:	03/11/2020	Nature of Claim:	TP
		Claim No:	1833921775SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ4696J	Engine No:	LEB5561549
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71034516
Reg. Date:	11/07/2017 (Man. Year: 2017)	Odometer:	55578 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,302.20	7,889.44	9,412.76	54.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,200.00	2,520.00	5,680.00	69.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,502.20	10,409.44	15,092.76	59.18
Approved Total (Overridden) (S\$)		8,000.00		
(S\$)	25,502.20	8,000.00	17,502.20	68.63
+ GST 7.00/7.00% (S\$)	1,785.15	560.00	1,225.15	68.63
Nett Amount (S\$)	27,287.35	8,560.00	18,727.35	68.63
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		9,396.45		
Global Sum Settlement (S\$)		9,300.00		

INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 04/11/2020 Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
 AutoPoint
 Singapore 568047

3/30/2021

Adjuster Report

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	920.00 FL	*- FL
2	1		*BONNET ISOLATOR	Not Necessary	105.00 FL	*- FL
3	1		*HEAD LAMP LH	Cut	2,180.00 FL	*1,544.00 FL
4	1		*HEAD LAMP LOWER BRACKET LH	Not Necessary	86.30 FL	*- FL
5	1		*FRONT BUMPER	Dented / Cut	1,250.00 FL	*950.80 FL
6	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	79.00 FL	*- FL
7	1		*FRONT FENDER LH	Dented	640.00 FL	*640.00 FL
8	1		*FRONT FENDER INNER SHIELD LH	Not Necessary	140.00 FL	*- FL
9	1		*FRONT FENDER HYBRID EMBLEM	Necessary	65.90 FL	*65.90 FL
10	1		*FRONT FENDER QUARTER GLASS LH	Scratched	592.75 FL	*592.75 FL
11	1		*FRONT FENDER QUARTER GLASS MOULDING LH	Necessary	86.50 FL	*86.50 FL
12	1		*FRONT WHEEL BEARING LH	Damaged	230.00 FL	*135.60 FL
13	1		*FRONT WHEEL BEARING HUB LH	Repeated	300.30 FL	*- FL
14	1		*FRONT ABSORBER LH	Distorted	425.00 FL	*325.00 FL
15	1		*FRONT KNUCKLE ARM LH	Distorted	450.60 FL	*360.80 FL
16	1		*FRONT LOWER ARM LH	Distorted	400.30 FL	*300.30 FL
17	1		*FRONT STABILIZER LINK LH	Not Necessary	195.70 FL	*- FL
18	1		*FRONT STABILIZER BAR	Not Necessary	280.00 FL	*- FL
19	1		*SIDE MIRROR ASSY LH	Broken	780.20 FL	*780.20 FL
20	1		*FRONT DOOR LH	Dented	1,250.00 FL	*1,250.00 FL
21	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	175.60 FL	*- FL
22	1		*FRONT DOOR WEATHER STRIP INNER LH	Not Necessary	205.00 FL	*- FL
23	1		*FRONT DOOR WEATHER STRIP OUTER LH	Not Necessary	210.80 FL	*- FL
24	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	680.50 FL	*- FL
25	2		*FRONT DOOR HINGE LH	Not Necessary	97.20 FL	*- FL
26	1		*FRONT DOOR BLACK STICKER LH	Necessary	96.90 FL	*96.90 FL
27	1		*REAR SLIDING DOOR LH	Dented	1,305.00 FL	*1,305.00 FL
28	1		*REAR SLIDING DOOR WINDOW MOULDING LH	Not Necessary	185.60 FL	*- FL
29	1		*REAR SLIDING DOOR BLACK STICKER LH	Necessary	86.30 FL	*86.30 FL
30	1		*REAR SLIDING DOOR WEATHER STRIP INNER LH	Not Necessary	268.00 FL	*- FL
31	1		*REAR SLIDING DOOR WEATHER STRIP OUTER LH	Not Necessary	225.00 FL	*- FL
32	1		*REAR SLIDING DOOR INNER TRIM BOARD LH	Not Necessary	750.00 FL	*- FL
33	1		*REAR FENDER LH	Dented	1,112.00 FL	*1,112.00 FL
34	1		*REAR FENDER INNER SHIELD LH	Not Necessary	92.50 FL	*- FL
35	1		*REAR FENDER INNER TRIM LH	Not Necessary	468.00 FL	*- FL
36	1		*REAR FENDER QUARTER GLASS MOULDING LH	Necessary	98.50 FL	*98.50 FL
37	1		*REAR WHEEL BEARING LH	Not Necessary	421.00 FL	*- FL
38	1		*REAR WHEEL BEARING HUB LH	Not Necessary	342.00 FL	*- FL
39	1		*REAR ABSORBER LH	Not Necessary	436.00 FL	*- FL
40	1		*REAR AXLE	Not Necessary	1,450.00 FL	*- FL
41	1		*REAR BUMPER	Not Necessary	1,025.00 FL	*- FL
42	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	64.90 FL	*- FL
43	1		*TAIL LAMP LH	Not Necessary	629.10 FL	*- FL
44	1		*TAIL LAMP LOWER BRACKET LH	Not Necessary	70.30 FL	*- FL
45	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
48	1		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
50	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*REAR FENDER QUARTER GLASS SEALANT	Necessary	80.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Necessary	30.00 FS	*15.00 FS
53	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
54	1		*REAR SLIDING DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,492.75	9,835.55
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,190.55	1,946.11
Total Parts (\$\$)	17,302.20	7,889.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	500.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	1,400.00	1,000.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	1,400.00	1,000.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	1,400.00	0.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	1,400.00	0.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	300.00	150.00
8	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	300.00	0.00
9	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
10	TO RNR REAR SLIDING DOOR MECHANISM TO FACILITATE REPAIRS	New	200.00	80.00
11	TO RNR REAR FENDER QUARTER GLAS TO FACILITATE REPAIRS	New	200.00	40.00
12	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
13	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
14	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			8,200.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >