

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Att: Motor Claims Dept

ACCIDENT INVOLVING GBB8681Y [YOUR INSURED] & SLQ4696J [OUR CLIENT]
ON 03/11/2020.

ESTIMATED REPAIR COSTS FOR SLQ4696J

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET <i>HW</i>	\$ 920.00	X
1PC	BONNET ISOLATOR <i>HW</i>	\$ 105.00	X
1PC	HEAD LAMP LH <i>cut</i>	\$ 2,180.00	✓
1PC	HEAD LAMP LOWER BRACKET LH <i>HW</i>	\$ 86.30	X
1PC	FRONT BUMPER <i>Destroyed / cut</i>	\$ 1,250.00	✓
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$39.50 EACH <i>HW</i>	\$ 79.00	X
1PC	FRONT FENDER LH <i>Destroyed</i>	\$ 640.00	✓
1PC	FRONT FENDER INNER SHIELD LH <i>HW</i>	\$ 140.00	X
1PC	FRONT FENDER 'HYBRID' EMBLEM <i>HW</i>	\$ 65.90	✓
1PC	FRONT FENDER QUARTER GLASS LH <i>Scratched</i>	\$ 592.75	✓
1PC	FRONT FENDER QUARTER GLASS MOULDING LH <i>HW</i>	\$ 86.50	✓
1PC	FRONT WHEEL BEARING LH <i>2 Down</i>	\$ 230.00	2L
1PC	FRONT WHEEL BEARING HUB LH <i>2 replaced</i>	\$ 300.30	X
1PC	FRONT ABSORBER LH <i>2 distance</i>	\$ 425.00	2L
1PC	FRONT KNUCKLE ARM LH <i>2 distance</i>	\$ 450.60	2L
1PC	FRONT LOWER ARM LH <i>2 distance</i>	\$ 400.30	2L
1PC	FRONT STABILIZER LINK LH <i>HW</i>	\$ 195.70	X
1PC	FRONT STABILIZER BAR <i>HW</i>	\$ 280.00	X
1PC	SIDE MIRROR ASSY LH <i>broken</i>	\$ 780.20	✓
1PC	FRONT DOOR LH <i>Destroyed</i>	\$ 1,250.00	✓
1PC	FRONT DOOR WINDOW MOULDING LH <i>Flame HW</i>	\$ 175.60	X
1PC	FRONT DOOR WEATHER STRIP INNER LH <i>HW</i>	\$ 205.00	X
1PC	FRONT DOOR WEATHER STRIP OUTER LH <i>HW</i>	\$ 210.80	X
1PC	FRONT DOOR INNER TRIM BOARD LH <i>HW</i>	\$ 680.50	X
2PCS	FRONT DOOR HINGE LH @ \$48.60 EACH <i>HW</i>	\$ 97.20	X
1PC	FRONT DOOR BLACK STICKER LH <i>HW HW</i>	\$ 96.90	2L
1PC	REAR SLIDING DOOR LH <i>Destroyed</i>	\$ 1,305.00	✓
1PC	REAR SLIDING DOOR WINDOW MOULDING LH <i>HW</i>	\$ 185.60	X
1PC	REAR SLIDING DOOR BLACK STICKER LH <i>HW HW</i>	\$ 86.30	2L
1PC	REAR SLIDING DOOR WEATHER STRIP INNER LH <i>HW</i>	\$ 268.00	X

1PC	REAR SLIDING DOOR WEATHER STRIP OUTER LH H4	\$ 225.00	X
1PC	REAR SLIDING DOOR INNER TRIM BOARD LH H4	\$ 750.00	X
1PC	REAR FENDER LH Denda	\$ 1,112.00	✓
1PC	REAR FENDER INNER SHIELD LH H4	\$ 92.50	X
1PC	REAR FENDER INNER TRIM LH H4	\$ 468.00	X
1PC	REAR FENDER QUARTER GLASS MOULDING LH H4 H4c	\$ 98.50	X ✓
1PC	REAR WHEEL BEARING LH H4	\$ 421.00	X
1PC	REAR WHEEL BEARING HUB LH H4	\$ 342.00	X
1PC	REAR ABSORBER LH H4	\$ 436.00	X
1PC	REAR AXLE H4	\$ 1,450.00	X
1PC	REAR BUMPER H4	\$ 1,025.00	X
1PC	REAR BUMPER SIDE RETAINER LH H4	\$ 64.90	X
1PC	TAIL LAMP LH H4	\$ 629.10	X
1PC	TAIL LAMP LOWER BRACKET LH H4	\$ 70.30	X

PARTS SUM: \$ 20,952.75

PARTS LESS 20%: \$ 4,190.55

PARTS TOTAL: \$ 16,762.20

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY BONNET INNER TRIM CLIPS H4	\$ 50.00	X
*	TO SUPPLY HEAD LAMP CLIPS H4	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER CLIPS H4c	\$ 50.00	30/-
*	TO SUPPLY REAR BUMPER CLIPS H4	\$ 50.00	X
*	TO SUPPLY REAR FENDER SEALANT H4c	\$ 80.00	40/-
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS H4	\$ 50.00	X
*	TO SUPPLY REAR FENDER QUARTER GLASS SEALANT H4c	\$ 80.00	20/-
*	TO SUPPLY REAR FENDER QUARTER GLASS DAMPING SEAL H4c	\$ 30.00	15/-
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS H4	\$ 50.00	X
*	TO SUPPLY REAR SLIDING DOOR INNER TRIM CLIPS H4	\$ 50.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	\$ 500.00	120/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	\$ 1,400.00	1000/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	\$ 1,400.00	1000/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	\$ 1,400.00	X repaired
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	\$ 1,400.00	X repaired
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-

*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 300.00 150/-
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 300.00 44
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 60/-
*	TO RNR REAR SLIDING DOOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 80/-
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$ 200.00 40/-
*	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	\$ 100.00 44
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 44

LABOUR & S/N TOTAL: \$ 8,740.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 25,502.20

04/11/2025 @ 1730hrs

Not Antenna

L/sure 7 day.

Man

LKK Auto

Check part prices,



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: