

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012020/ATF3Q2

Date: 30/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00003402000
Claimant Vehicle No :	SCV204C	Insured Vehicle No :	PC8097M
Date of Loss:	29/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D204155/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCV204C	Engine No:	G4LCJU063244
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCU41BTKU451022
Reg. Date:	20/10/2018 (Man. Year: 2018)	Odometer:	17286 km
Colour:	Red		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,685.04	3,820.08	6,864.96	64.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	1,170.00	1,610.00	57.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,465.04	4,990.08	8,474.96	62.94
Approved Total (Overridden) (\$\$)		3,900.00		
(\$\$)	13,465.04	3,900.00	9,565.04	71.04
+ GST 7.00/7.00% (\$\$)	942.55	273.00	669.55	71.04
Nett Amount (\$\$)	14,407.59	4,173.00	10,234.59	71.04

INSPECTION

Date of Assignment: 26/11/2020

Date Inspected: 05/11/2020 Inspected At:

RICO 60 AUTO SERVICES PTE LTD
(HQ)
8, KAKI BUKIT AVENUE 4, #02-24,
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2020)
Parts:	143	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCV204C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented	589.00 FL	*589.00 FL
2	1		*FRONT FENDER BRACKET RH	Not Necessary	86.00 FL	*- FL
3	1		*FRONT FENDER INNER SHIELD RH	Torn	133.60 FL	*133.60 FL
4	1		*FRONT FENDER INNER INNER PANEL RH	Not Necessary	332.00 FL	*- FL
5	1		*FRONT BUMPER	Crushed	546.00 FL	*546.00 FL
6	1		*FRONT BUMPER LOWER CENTER GRILLE	Not Necessary	49.90 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP RH	Cracked	345.00 FL	*236.00 FL
8	1		*FRONT BUMPER TOP RUBBER SEAL	Not Necessary	42.70 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER LH/RH	O/s Damaged	108.00 FL	*54.00 FL
10	1		*FRONT BUMPER INNER SPONGE	Cracked	154.00 FL	*154.00 FL
11	2		*FRONT BUMPER CORNER RETAINER LH/RH	Not Necessary	31.60 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	384.00 FL	*289.00 FL
13	1		*FRONT BUMPER TOP RETAINER	Not Necessary	50.80 FL	*- FL
14	1		*FRONT BUMPER LOWER BEAM	Not Necessary	215.00 FL	*- FL
15	1		*FRONT BUMPER LOWER RUBBER MOULDING	Not Necessary	94.90 FL	*- FL
16	1		*FRONT BUMPER LOWER UNDER COVER	Not Necessary	145.00 FL	*- FL
17	1		*FRONT HEADLAMP LH/RH	O/s Cut	1,780.00 FL	*774.00 FL
18	2		*FRONT HEADLAMP LOWER BRACKET LH/RH	Not Necessary	308.00 FL	*- FL
19	1		*FRONT GRILLE	Not Necessary	214.00 FL	*- FL
20	1		*FRONT GRILLE CHROME	Not Necessary	158.00 FL	*- FL
21	1		*FRONT GRILLE LOGO EMBLEM	Not Necessary	26.80 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Not Necessary	782.00 FL	*- FL
23	1		*WIPER WASHER TANK	Deformed	143.00 FL	*143.00 FL
24	1		*FRONT LOWER ARM	Bent	354.00 FL	*354.00 FL
25	1		*FRONT SHOCK ABSORBER	Bent	456.00 FL	*456.00 FL
26	1		*FRONT KNUCKLE ARM	Damaged	589.00 FL	*352.00 FL
27	1		*STEERING RACK AND PINION	Not Necessary	2,415.00 FL	*- FL
28	1		*DRIVE SHAFT	Not Necessary	1,359.00 FL	*- FL
29	1		*FRONT KNUCKLE BEARING	Necessary	232.00 FL	*232.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*FRONT LINK	Not Necessary	132.00 FL	*- FL
31	1		*SET FRONT FENDER INNER SHIELD VERTICAL CLIPS	Not Necessary	40.00 FS	*- FS
32	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
33	1		*SET FRONT BUMPER RIVET	Necessary	50.00 FS	*10.00 FS
34	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
35	1		*WHEEL RIM	Bent	250.00 FS	*200.00 FS
36	1		*SET WHEEL CAP	Cut	400.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,136.30	4,682.60
- List Item Discount on L Items 20.00/20.00% (\$)	2,451.26	862.52
Total Parts (\$)	10,685.04	3,820.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	800.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	800.00	400.00
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
4	TUFF COAT	New	50.00	20.00
5	WIRING,BULB CHECKING	New	50.00	30.00
6	REFOCUS HEADLAMP BEAM	New	60.00	0.00
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	550.00	220.00
8	RESET ABS LIGHT	New	350.00	0.00
Gross Labour Cost (\$\$)			2,780.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >