

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20012023/QPS3Q2

Date: 17/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900006394
Claimant
Vehicle No : SML8006P **Insured Vehicle No :** SMH1188P
Date of Loss: 01/11/2020 **Nature of Claim:** TP **Claim No:** 2286943273SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML8006P**
 Make & Model: HONDA FIT, 1.5 HYBRID (A) Engine No: LEB1453141
 Reg. Date: 04/06/2019 (Man. Year: 2019) Chassis No: GP51343673
 Colour: Red Odometer: 101892 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Grenlander 6 mm Rear Left Side: Grenlander 6 mm
 Front Right Side: Grenlander 6 mm Rear Right Side: Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,172.88	6,158.48	11,014.40	64.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	2,880.00	2,340.00	44.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,392.88	9,038.48	13,354.40	59.64
Approved Total (Overridden) (S\$)		7,250.00		
(S\$)	22,392.88	7,250.00	15,142.88	67.62
+ GST 7.00/7.00% (S\$)	1,567.50	507.50	1,060.00	67.62
Nett Amount (S\$)	23,960.38	7,757.50	16,202.88	67.62
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,244.95		
Global Sum Settlement (S\$)		8,240.00		

INSPECTION

Date of Assignment: 04/11/2020
 Date Inspected: 04/11/2020 Inspected At: My Car Consultant Pte Ltd - Ubi (HQ)
 53 Ubi Ave 1, #01-33 Paya Ubi
 Industrial Park
 Singapore 408934
 Estimated Period of Repair: 8.0 days

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	880.20 FL	*880.20 FL
2	2		*TAILGATE STOPPER	Serviceable	57.00 FL	*- FL
3	1		*TAILGATE INNER LOCK	Jammed	198.20 FL	*198.20 FL
4	2		*TAILGATE HINGE	Serviceable	96.00 FL	*- FL
5	1		*TAILGATE STRICKER	Serviceable	55.60 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Broken	178.30 FL	*178.30 FL
7	1		*TAILGATE INNER TRIM BOARD	Crushed	486.60 FL	*486.60 FL
8	1		*TAILGATE OUTER CHROME MOULDING	Serviceable	336.20 FL	*- FL
9	1		*TAILGATE WINDSCREEN MOULDING	Necessary	145.00 FL	*145.00 FL
10	1		*TAILGATE EMBLEM	Serviceable	68.00 FL	*- FL
11	1		*TAILGATE EMBLEM FIT	Necessary	62.00 FL	*62.00 FL
12	1		*TAILGATE EMBLEM HYBRID	Serviceable	82.00 FL	*- FL
13	1		*TAILGATE DETECTOR	Crushed	198.20 FL	*120.00 FL
14	1		*TAILGATE KEY DETECTOR	Crushed	157.00 FL	*90.00 FL
15	2		*TAILGATE REFLECTOR	Serviceable	590.00 FL	*- FL
16	2		*REAR NUMBER PLATE LAMP	Serviceable	108.00 FL	*- FL
17	1		*REAR BUMPER	Crushed	587.00 FL	*510.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Broken	116.60 FL	*116.60 FL
19	2		*REAR BUMPER REFLECTOR	Serviceable	164.00 FL	*- FL
20	1		*REAR BUMPER CENTRE GARNISH	Scratched	146.00 FL	*146.00 FL
21	1		*REAR BUMPER SIDE GARNISH	N/S Crushed	158.00 FL	*79.00 FL
22	1		*REAR BUMPER DIFFUSER	Crushed	321.00 FL	*182.00 FL
23	2		*TAILAMP	O/S Cracked / N/S Scratched	978.00 FL	*610.00 FL
24	2		*REAR FENDER COWLING	Serviceable	318.00 FL	*- FL
25	2		*REAR FENDER INNER TRIM	Deformed	796.00 FL	*796.00 FL
26	1		*REAR FENDER INNER TRIM COVER RH	Cracked	168.00 FL	*168.00 FL
27	1		*REAR END PANEL	Dented	468.00 FL	*448.00 FL
28	1		*REAR END PANEL TOP GARNISH	Crushed	212.20 FL	*130.00 FL
29	1		*REAR FLOOR PANEL	Crushed	985.00 FL	*785.00 FL
30	1		*REAR FLOOR PANEL TOP BOARD	Crushed	554.70 FL	*554.70 FL
31	1		*REAR FLOOR PANEL TOP BOARD SPONGE	Serviceable	498.00 FL	*- FL
32	1		*REAR SPARE TYRE BOLT	Serviceable	19.50 FL	*- FL
33	1		*EXHAUST SILENCER	Serviceable	512.00 FL	*- FL
34	1		*EXHAUST PIPE HEAT SHIELD	Serviceable	114.30 FL	*- FL
35	2		*EXHAUST PIPE SILENCER MOUNTING	Serviceable	64.00 FL	*- FL
36	1		*SET REAR HYBRID BATTERY	Broken	8,500.00 FL	*500.00 FL
37	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Serviceable	50.00 FS	*- FS
38	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
39	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00 FS	*30.00 FS
40	1		*SET TAILAMP CLIPS	Serviceable	30.00 FS	*- FS
41	1		*REAR NUMBER PLATE WITH CASING	Crushed	50.00 FS	*30.00 FS
42	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
43	1		*SET REAR FENDER SIDE INNER TRIM CLIPS	Serviceable	50.00 FS	*- FS
44	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*30.00 FS
45	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*30.00 FS
46	1		*REAR FLOOR PANEL INSULATOR	Serviceable	250.00 FS	*- FS
47	1		*REAR FLOOR PANEL SEALANT	Necessary	200.00 FS	*30.00 FS
48	1		*REVERSE CAMERA	Serviceable	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	21,048.60 7,595.60
					- List Item Discount on L Items 20.00/20.00% (\$)	3,875.72 1,437.12
					Total Parts (\$)	17,172.88 6,158.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,200.00
2	PANEL BEATING ON AFFECTED AREAS	New	1,600.00	1,200.00
3	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
4	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	30.00
5	REMOVE AND REFIX REAR UPHOLSTERY	New	400.00	60.00
6	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
7	REMOVE AND REFIT TAILGATE MECHANISM	New	150.00	60.00
8	CHECK AND TEST FOR WATER LEAKAGE	New	50.00	0.00
9	CHECK AND RESET FAULT CODE LIGHT ON	New	250.00	0.00
10	RESETTING HYBRID SYSTEM AND PROGRAMM ECU	New	600.00	100.00
11	TO RESPRAY UNDERCOATING	New	100.00	40.00
12	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	40.00
Gross Labour Cost (\$\$)			5,220.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >