

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012026/DVD3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30778419011	
Claimant Vehicle No :	SMA2189S	Insured Vehicle No :	SKE4058B	
Date of Loss:	30/10/2020	Nature of Claim:	TP	Claim No: SNM20D204111/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA2189S				
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGJH695311		
Reg. Date:	31/05/2018 (Man. Year: 2017)	Chassis No:	KNAFJ411MJ5764842		
Colour:	Grey	Odometer:	33628 km		
Engine Capacity:	1591 cc				
Market Value/New Car Price:	N/A				
Sum Insured (\$\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,110.18	4,774.72	18,335.46	79.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	1,680.00	1,890.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,680.18	6,454.72	20,225.46	75.81
Approved Total (Overridden) (\$\$)		5,150.00		
(\$\$)	26,680.18	5,150.00	21,530.18	80.70
+ GST 7.00/7.00% (\$\$)	1,867.61	360.50	1,507.11	80.70
Nett Amount (\$\$)	28,547.79	5,510.50	23,037.29	80.70

INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 04/11/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2020)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA2189S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Not Necessary	1,306.00 FL	*- FL
2	1	*FRONT BONNET INNER TRIM BOARD	Not Necessary	482.74 FL	*- FL
3	1	*HEAD LAMP LH	Scratched	1,311.00 FL	*972.00 FL
4	1	*HEAD LAMP LOWER BRACKET LH	Not Necessary	319.00 FL	*- FL
5	1	*HEAD LAMP WIREHARNESS	Not Necessary	2,095.00 FL	*- FL
6	1	*FRONT BUMPER	Dented	916.08 FL	*702.90 FL
7	2	*FRONT BUMPER SIDE RETAINER L+R	Serviceable	85.60 FL	*- FL
8	1	*FRONT BUMPER TOP RUBBER MOULDING	Not Necessary	279.27 FL	*- FL
9	1	*FRONT BUMPER KIA LOGO	Not Necessary	102.55 FL	*- FL
10	1	*FRONT GRILLE	Not Necessary	725.20 FL	*- FL
11	1	*FRONT GRILLE CHROME MOULDING	Not Necessary	327.18 FL	*- FL
12	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	434.51 FL	*- FL
13	4	*FRONT BUMPER SENSOR	Not Necessary	807.12 FL	*- FL
14	4	*FRONT BUMPER SENSOR HOLDER	Not Necessary	170.84 FL	*- FL
15	1	*FRONT BUMPER SENSOR WIRE HARNESS	Not Necessary	452.97 FL	*- FL
16	2	*HEAD LAMP L+R	Repeated	2,800.00 FL	*- FL
17	2	*HEAD LAMP BRACKET L+R	Not Necessary	156.34 FL	*- FL
18	1	*FRONT SUPPORT PANEL	Not Necessary	794.00 FL	*- FL
19	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	372.19 FL	*- FL
20	1	*BRACE PANEL	Not Necessary	398.17 FL	*- FL
21	1	*FRONT FENDER LH	Dented	640.00 FL	*640.00 FL
22	1	*FRONT FENDER INNER SHIELD LH	Deformed	126.00 FL	*126.00 FL
23	1	*FRONT FENDER LAMP LH	Not Necessary	88.00 FL	*- FL
24	1	*FRONT DOOR LH	Dented	1,644.00 FL	*1,083.00 FL
25	1	*FRONT DOOR WINDOW MOULDING LH	Not Necessary	152.00 FL	*- FL
26	1	*FRONT DOOR WEATHER STRIP	Not Necessary	251.00 FL	*- FL
27	1	*FRONT WHEEL BEARING LH	Damaged	318.00 FL	*144.10 FL
28	1	*FRONT WHEEL BEARING HUB LH	Repeated	355.00 FL	*- FL
29	1	*FRONT KNUCKLE ARM LH	Distorted	616.00 FL	*385.00 FL
30	1	*FRONT LOWER ARM LH	Distorted	643.00 FL	*371.80 FL
31	1	*FRONT ABSORBER LH	Distorted	583.00 FL	*336.00 FL
32	1	*STABILIZER BAR	Not Necessary	329.00 FL	*- FL
33	1	*STABILIZER LINK LH	Not Necessary	165.00 FL	*- FL
34	1	*STEERING RACK & PINION ASSY	Not Necessary	1,833.00 FL	*- FL
35	1	*DRIVE SHAFT	Not Necessary	1,989.00 FL	*- FL
36	1	*SIDE MIRROR ASSY L/H (NPA)	Not Necessary	0.00 FL	*- FL
37	1	*FRONT RIM LH	Cut	889.20 FS	*450.00 FS
38	1	*FRONT NUMBER PLATE	Not Necessary	40.00 FS	*- FS
39	1	*FRONT BONNET INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
40	1	*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
41	1	*FRONT GRILLE CLIPS	Not Necessary	20.00 FS	*- FS
42	1	*FRONT LOWER GRILLE CLIPS	Not Necessary	20.00 FS	*- FS
43	1	*SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT BUMPER TOP RUBBER MOULDING CLIPS	Not Necessary	20.00 FS	*- FS
45	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*20.00 FS
46	1		*TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	25,516.96	5,250.80
- List Item Discount on L Items 10.00/10.00% (\$)	2,406.78	476.08

Total Parts (\$)	23,110.18	4,774.72
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,200.00	700.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,000.00	700.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
4	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	300.00	150.00
5	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT	New	150.00	60.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
8	TO RNR FRONT BUMPER SENSOR TO ASSIST WORK LOAD	New	120.00	0.00
Gross Labour Cost (S\$)			3,570.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >