

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012029/R1QF3Q2

Date: 09/02/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00026852000

Claimant Vehicle No : SLU8466J Insured Vehicle No : GBE1317E

Date of Loss: 30/10/2020 Nature of Claim: TP Claim No: SNM20D204148/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU8466J**

Make & Model: VOLVO XC60, 2.0 T5 (A) Engine No: B4204T232303113

Reg. Date: 15/12/2017 (Man. Year: 2017) Chassis No: YV1UZ10ACJ1031689

Colour: Grey Odometer: 37728 km

Engine Capacity: 1969 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	26,943.39	20,568.06	6,375.33	23.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,200.00	9,425.00	3,775.00	28.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>40,143.39</b>	<b>29,993.06</b>	<b>10,150.33</b>	<b>25.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,810.04</b>	<b>2,099.51</b>	<b>710.53</b>	<b>25.29</b>
<b>Nett Amount (S\$)</b>	<b>42,953.43</b>	<b>32,092.57</b>	<b>10,860.86</b>	<b>25.29</b>

### INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 10/11/2020 Inspected At:

Wearnes Automotive Pte Ltd  
(Alexandra Road)  
249 Alexandra Road  
Singapore 159935

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2021)
<b>Parts:</b>	M1-SUV	VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLU8466J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET FRT XC60 18	Bent	3,025.60 FS	*2,723.04 FS
2	1		*BONNET HINGE RH XC60	Serviceable	233.70 FS	*- FS
3	1		*BONNET HINGE LH XC60	Serviceable	233.70 FS	*- FS
4	1		*BONNET LOCK RH S90 1	Serviceable	185.50 FS	*- FS
5	1		*BONNET LOCK LH XC60	Serviceable	148.40 FS	*- FS
6	1		*BONNET LOCK CONTRO	Cracked	140.10 FS	*126.09 FS
7	1		*BONNET CABLE OUTER	Cut	78.00 FS	*70.20 FS
8	1		*LOCK BRACE LH XC90 1	Bent	78.40 FS	*70.56 FS
9	1		*LOCK BRACE RH XC90 1	Bent	78.40 FS	*70.56 FS
10	1		*SOUND ABSORBER BONNE	Serviceable	493.80 FS	*- FS
11	1		*BUMPER COVER FRT XC6	Deformed	1,743.20 FS	*1,568.88 FS
12	1		*RADIATOR GRILLE XC60	Cracked	920.50 FS	*828.45 FS
13	1		*BUMPER BRACKET SIDE	Cracked	72.90 FS	*65.61 FS
14	1		*BUMPER BRACKET SIDE	Cracked	72.90 FS	*65.61 FS
15	1		*TOW COVER FRT XC60 1	Serviceable	77.70 FS	*- FS
16	1		*BUMPER BRACKET FRT L	Cracked	72.90 FS	*65.61 FS
17	1		*BUMPER BRACKET FRT R	Cracked	72.90 FS	*65.61 FS
18	1		*V031425175/BUMPER GR	Serviceable	458.20 FS	*- FS
19	1		*BUMPER FOAM FRT XC60	Cracked	359.60 FS	*323.64 FS
20	1		*LOUVRE DECOR LH XC60	Serviceable	32.10 FS	*- FS
21	1		*LOUVRE DECOR RH XC60	Serviceable	29.20 FS	*- FS
22	1		*COVER DECOR LH T5 XC	Serviceable	33.40 FS	*- FS
23	1		*COVER DECOR RH T5 XC	Serviceable	33.40 FS	*- FS
24	1		*RETAINER SENSOR CTR	Serviceable	20.30 FS	*- FS
25	1		*RETAINER SENSOR CTR	Serviceable	21.50 FS	*- FS
26	1		*BRACKET DECOR LH XC6	Serviceable	45.30 FS	*- FS
27	1		*BRACKET DECOR RH XC6	Serviceable	40.80 FS	*- FS
28	1		*HEADLAMP LED LH XC60	Cracked	2,453.20 FS	*2,207.88 FS
29	1		*HEADLAMP LED RH XC60	Cracked	2,453.20 FS	*2,207.88 FS
30	1		*HEADLAMP CONTROL UNI	Serviceable	480.40 FS	*- FS
31	1		*HEADLAMP CONTROL UNI	Serviceable	480.40 FS	*- FS
32	1		*CROSS MEMBER	Bent	153.00 FS	*137.70 FS
33	1		*V032216660/BUMPER RA	Bent	1,403.90 FS	*1,263.51 FS
34	1		*TAILGATE REAR XC60 1	Cut	2,852.20 FS	*2,566.98 FS
35	1		*EMBLEM VOLVO REAR	Necessary	96.70 FS	*87.03 FS
36	1		*EMBLEM XC60 CH 365	Necessary	100.80 FS	*90.72 FS
37	1		*EMBLEM T5 XC60 S80	Necessary	92.50 FS	*83.25 FS
38	1		*EMBLEM AWD XC90 16	Necessary	82.10 FS	*73.89 FS
39	1		*V039847249/BUMPER CO	Cut	1,401.00 FS	*1,322.46 FS
40	1		*TOW COVER REAR XC60	Missing	77.70 FS	*69.93 FS
41	1		*PROTECTING PLATE REA	Serviceable	675.30 FS	*- FS
42	1		*BUMPER BRACKET CTR R	Cracked	72.90 FS	*65.61 FS
43	1		*BUMPER BRACKET LHR X	Serviceable	44.50 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*BUMPER BRACKET RHR X	Serviceable	44.50 FS	*- FS
45	10		*BLIND RIVET 4.0 *21 P	Necessary	32.00 FS	*28.80 FS
46	10		*BUMPER CLIP 8X8,5	Necessary	57.00 FS	*51.30 FS
47	1		*BUMPER INSTALLING MT	Necessary	87.70 FS	*78.93 FS
48	2		*EXTERIOR ADHESIVE GL	Necessary	498.80 FS	*448.92 FS
49	1		**D* WELDING PRIMER	Necessary	367.80 FS	*331.02 FS
50	1		*ADHESIVE TUBE CHEMIC	Not Necessary	725.00 FS	*- FS
51	1		*WINDSCREEN REAR XC60	Necessary	1,314.18 FS	*1,314.18 FS
52	2		*JC2D7026/SEALANT WIN	Necessary	287.10 FS	*287.10 FS
53	1		**D* PRIMER GLASS & P	Necessary	35.37 FS	*35.37 FS
54	1		*V001161436/*D* GLASS	Necessary	52.38 FS	*52.38 FS
55	1		*TAILGATE LAMP LH XC6	Scratched	141.75 FS	*141.75 FS
56	1		*AIR GUIDE XC60 18	Cracked	263.70 FS	*263.70 FS
57	1		*AIR GUIDE PANEL XC60	Cracked	124.29 FS	*124.29 FS
58	1		*AIR GUIDE SEAL LOWER	Necessary	123.48 FS	*123.48 FS
59	1		*FENDER CARRIER LH XC	Bent	184.41 FS	*184.41 FS
60	1		*AIR GUIDE SURROUND X	Cracked	170.28 FS	*170.28 FS
61	1		*SHIELD	Cracked	22.86 FS	*22.86 FS
62	1		*AIR INLET	Cracked	64.89 FS	*64.89 FS
63	1		*BUSH RADIATOR LH UPP	Necessary	15.93 FS	*15.93 FS
64	1		*PROTECTING PLATE REA	Bent	607.77 FS	*607.77 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>26,943.39</b>	<b>20,568.06</b>
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE REAR BUMPER,REAR SPOILER,TAILGATE,REAR TOW EYE COVER,BRACKETS,EMBLEMS,BONNET,BONNET LOCK,FRT BUMPER,HEADLAMPS,GRILLE,LOGO,BRACKETS,SUPPORT PANEL,ETC	New	5,600.00	3,200.00
2	TO PUTTY AND SPRAY PAINT ON REAR BUMPER,TAILGATE,TOW EYE COVER,BONNET,FRT BUMPER,ETC	New	3,500.00	2,800.00
3	TO REPLACE REAR WINDSCREEN	New	800.00	800.00
4	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	280.00	280.00
5	TO TRANSFER TAILGATE MECHANISM	New	800.00	250.00
6	TO FOCUS HEADLAMPS	New	175.00	170.00
7	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	525.00	525.00
8	TO INSTALL FRONT & REAR NUMBER PLATE WITH HOLDER	New	120.00	0.00
9	TO PUTTY AND SPRAY ON LHF FEND AND RHF FENDER	New	1,400.00	1,400.00
<b>Gross Labour Cost (S\$)</b>			<b>13,200.00</b>	<b>9,425.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >