

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20012031/GSD3E2

Date: 20/11/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800125338
Claimant Vehicle No :	SGH963X	Insured Vehicle No :	SMF2364B
Date of Loss:	02/11/2020	Nature of Claim:	TP
		Claim No:	1378255493SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH963X		
Make & Model:	MITSUBISHI LANCER, 1.6 (M)	Engine No:	4G18HH3654
Reg. Date:	30/05/2006 (Man. Year: 2006)	Chassis No:	JMYSNCS3A6U006437
Colour:	Blue	Odometer:	158281 km
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/11/2020	
Date Inspected:	04/11/2020 Inspected At:	Sin Seng Hong Spray Painting & Service (ubi) (HQ) 3023A UBI ROAD 1, #01-63 Singapore 408717
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE GARNISH	Deformed	0.00 F	*- F
2	1		*REAR BUMPER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
5	1		*REAR BUMPER BEAM	Bent	0.00 F	*- F
6	1		*REAR BUMPER LOWER SPOILER	Deformed	0.00 F	*- F
7	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
8	1		*REAR END PANEL	Bent	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
10	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
12	1		*BOOTLID	Bent	0.00 F	*- F
13	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
14	1		*BOOTLID LOCK	Cut	0.00 F	*- F
15	1		*BOOTLID RUBBER	Twisted	0.00 F	*- F
16	1		*BOOTLID SPOILER	Cracked	0.00 F	*- F
17	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
18	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
19	1		*REAR LH FENDER	Repair	0.00 F	*- F
20	1		*REAR RH FENDER	Repair	0.00 F	*- F
21	1		*STICKER	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >