

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20012033/R1QF3E2

**Date:** 07/12/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00061832000	
Claimant Vehicle No :	SMP5352M	Insured Vehicle No :	GBC4801P	
Date of Loss:	02/11/2020	Nature of Claim:	TP	Claim No: SNM20D204165/C02/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP5352M		
Make & Model:	NISSAN SERENA, 1.2 Highway Star Premium E-Power (A)	Engine No:	HR12092575K
Reg. Date:	30/09/2019 (Man. Year: 2019)	Chassis No:	JN1EBAC27Z0000146
Colour:	White	Odometer:	9887 km
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,598.88	7,963.36	1,635.52	17.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,741.00	4,061.00	1,680.00	29.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,339.88</b>	<b>12,024.36</b>	<b>3,315.52</b>	<b>21.61</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,073.79</b>	<b>841.71</b>	<b>232.08</b>	<b>21.61</b>
<b>Nett Amount (S\$)</b>	<b>16,413.67</b>	<b>12,866.07</b>	<b>3,547.60</b>	<b>21.61</b>

### INSPECTION

Date of Assignment:	04/11/2020	
Date Inspected:	04/11/2020	Inspected At: TC AutoClinic Pte Ltd (Leng Kee) 25 Leng Kee Road Singapore 159097
Estimated Period of Repair:	9.0 days	

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2020)
<b>Parts:</b>	M1-MPV	NISSAN SERENA 1.2 Highway Star Premium E-Power (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMP5352M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR BACK TAILGATE GLASS	Broken	4,015.00 FN	*4,015.00 FN
2	1		*DOOR BLACK TAILGATE	Bent	1,742.00 FN	*1,742.00 FN
3	1		*A FIN BACK DOOR TAILGATE GARNISH	Cracked	797.20 FN	*797.20 FN
4	1		*A FIN BACK DOOR (SERENA WORDING GARNISH)	Cracked	797.20 FN	*797.20 FN
5	1		*EMBLEM-REAR-HIGHWAY STAR	Necessary	50.90 FN	*50.90 FN
6	1		*EMBLEM-REAR-E POWER	Necessary	94.40 FN	*94.40 FN
7	1		*FACE-RR BUMPER	Deformed	1,414.00 FN	*1,414.00 FN
8	1		*SENSOR-REVERSE	Not Necessary	360.00 FS	*- FS
9	1		*COVER REVERSE SENSOR BRACKET LH	Necessary	96.30 FS	*96.30 FS
10	1		*COVER REVERSE SENSOR BRACKET RH	Necessary	96.30 FS	*96.30 FS
11	2		*COVER REVERSE SENSOR BRACKET CENTER	Necessary	145.00 FS	*145.00 FS
12	1		*FIN BACK DOOR SERENA	Repeated	797.20 FN	*- FN
13	1		*BUMPER B/DOOR RUBBER STOPPER	Necessary	9.10 FN	*9.10 FN
14	1		*FINISHER BACK DOOR LOWER GARNISH	Cracked	297.90 FN	*297.90 FN
15	1		*HANDLE-PULL	Cut	19.60 FN	*19.60 FN
16	1		*ORNAMENT-REAR EMBLEM	Necessary	79.90 FN	*79.90 FN
17	1		*A FIN BACK DOOR CHROME GARNISH	Repeated	797.20 FN	*- FN
18	1		*RR PANEL-LWR	Bent	215.00 FN	*215.00 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,824.20</b>	<b>9,869.80</b>
<b>- Nett Item Discount on N Items 20.00/20.00% (\$\$)</b>	2,225.32	1,906.44
<b>Total Parts (\$\$)</b>	<b>9,598.88</b>	<b>7,963.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	New	55.00	55.00
2	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	200.00	100.00
3	REPAIR / REPLACE REAR BUMPER, END PANEL, TAILGATE, RH REAR FENDER & LH REAR FENDER	New	1,400.00	560.00
4	RESPRAY REAR BUMPER, END PANEL, TAILGATE, LH REAR FENDER & RH REAR FENDER	New	1,250.00	750.00
5	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	New	120.00	120.00
6	SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	New	144.00	144.00
7	REFIX REAR WINDSCREEN	New	240.00	240.00
8	REMOVE / REFIX REAR SEAT, TRIM, CARPET & GARNISH TO FACILITATE REPAIR	New	240.00	0.00
9	SUPPLY & INSTALL 1 UNIT HELLA DRIVE RECORDER	New	357.00	357.00
10	QC & CONSULT CHECK (NPA)	New	0.00	-
11	CARWASH & VACUUM (NPA)	New	0.00	0.00
12	LABOUR TO VACUUM ALL SHATTERED GLASS & DEBRIS FROM INTERIOR OF VEHICLE TO FACILITATE REPAIR	New	15.00	15.00
13	REMOVE / REPLACE REAR END PANEL	New	280.00	280.00
14	APPLY SEALANT AND ANTI RUST TO REAR END PANEL	New	220.00	220.00
15	REMOVE / REFIX ROOF LINING TO FACILITATE REPAIR	New	420.00	420.00
16	RESPRAY REAR END PANEL, LH REAR FENDER & RH REAR FENDER	New	720.00	720.00
17	CONDUCT WATER TEST AFTER REPAIR	New	80.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>5,741.00</b>	<b>4,061.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >