Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20012034/ASD3Q2

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 19/02/2021

REFERENCE

Insured/Claimant: LIM KNG YAU Policy No: 1700041626

Date of Loss: 27/10/2020 Nature of Claim: OD Claim No: 9629521976SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR5653X

Make & Model: AUDI A4, 1.4 (A) Engine No: CVN040756

Reg. Date: 18/08/2017 (Man. Year: 2017) Chassis No: WAUZZZF48HA177989

Colour: Bronze Odometer: 162970 km

Engine Capacity: 1395 cc
Market Value/New Car

Price: S\$90,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,471.00	0.00	6,471.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,462.00	2,982.00	3,480.00	53.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,933.00	2,982.00	9,951.00	76.94
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,333.00	2,382.00	9,951.00	80.69
+ GST 7.00/7.00% (S\$)	863.31	166.74	696.57	80.69
Nett Amount (S\$)	13,196.31	2,548.74	10,647.57	80.69

INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 04/11/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Repair	2,181.00 FS	*- FS	
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	72.00 FS	*-FS	
3	1		*REAR BUMPER SPOILER	Not Necessary	246.00 FS	*- FS	
4	1		*REAR LIGHT REFLETOR - LH	Not Necessary	41.00 FS	*- FS	
5	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	44.00 FS	*- FS	
6	1		*REAR DOOR - LH	Repair	2,354.00 FS	*- FS	
7	1		*REAR DOOR OUTER SEAL - LH	Not Necessary	203.00 FS	*- FS	
8	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS	
9	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS	
10	1		*SEALING STRIP	Not Necessary	16.00 FS	*- FS	
11	1		*REAR DOOR ATTACMENT PARTS	Not Necessary	563.00 FS	*- FS	
12	1		*REAR DOOR CATCH	Not Necessary	119.00 FS	*- FS	
13	1		*REAR BUMPER RIM - LH (NPA)	Cut	0.00FS	*-FS	
14	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS	
15	1		*REAR BUMPER SECURING STRIP	Not Necessary	220.00 FS	*- FS	
F=Franchise part. S=SpcNett.							
				Total Parts (S\$)	6,471.00	0.00	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	New	360.00	360.00				
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI- LOCK SYSTEM AND POWER WINDOR DEVICES. INSPECT FOR DAMAGES.	New -	280.00	0.00				
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,450.00	500.00				
4	TO RESPRAY REAR BUMPER, LHS REAR FENDER AND LHS REAR DOOR.	New	2,900.00	1,650.00				
5	TO RENEW LHS RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00				
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00				
	Gross Labour Cost (S\$)		6,462.00	2,982.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >