

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20012035/EYD3E2

**Date:** 10/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2070133260	
<b>Claimant Vehicle No :</b> SLZ5407Z	<b>Insured Vehicle No :</b> SJY8330U	
Date of Loss: 30/10/2020	Nature of Claim: TP	Claim No: 2935970594SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ5407Z		
Make & Model:	HONDA CIVIC, 1.8 L 5AT (A)	Engine No:	R18A14002279
Reg. Date:	29/10/2008 (Man. Year: 2008)	Chassis No:	JHMFD16309S200246
Colour:	Black	Odometer:	274107 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	03/11/2020		
Date Inspected:	04/11/2020	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	4.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REVERSE SENSOR	Broken	0.00 F	*- F
5	1		*REAR END PANEL	Repair	0.00 F	*- F
6	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
7	1		*BOOTLID	Dented	0.00 F	*- F
8	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
9	1		*BOOTLID LAMP LH	Cut	0.00 F	*- F
10	1		*BOOTLID LOCK	Bent	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (\$\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**