ASS. REC. BY:	CS/CTI200112036/Kvf3
Kenneth	SSICNMENT
From: Date:	Veh No: GBH 628H Yr Regn: 12, 17 Type: M.Car / M.Cycle / Bus / Van Korry Taxl / Prime Mover / Truck / Traller or Make: MS Cobsta c.c 2953 Colour AC: Insured / Std / NI / NA Sp.Reading 25, 1565 T/Radio: Insured / Std / NI / NA
Insured: SJV 890M Policy No. DMPCSNW00011282000 Claims No. SNM20D204074/C02/TAYHP Sum Insured: Excess: (Client's Record) Make of Veh:	Sp.Reading 5/363 T/Radio: Insured / Std / NI / NA Eng/No: C/No: TNISCZF 247 0861029 Gen. Cond: Good Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modl: NII S/Rim / STD A/Rim or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value:	Tyre Size: F: PSR 15XP R: 155R 12X8(D) BS 10UN 1 EXNOVA 1 GY 1 FS 1 LIZA 1 MIC 1 OHTSU 1 PIR 1 SUMI 1 TOYO 1 YOKO or
IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: O2 days Res.: Yes or No Lum Sum: /-B.1 % 3 Val.: Yes or No	R/Bai. 9 mm R/Bai. 9 9 mm L/Bai. 9 mm L/Bai. 9 9 mm D.O.A. 27/10/20 D.O.I. 10/11/2020 Survey held at
Date:Person Contacted: Vehicle: IN/OUT Date / Time Action / Instruction 28/4/21 Final fig \$1625.80 confirmed by em	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or The U/C / Chassis frame / Body Structure affected due to collision.
Einal fig \$1625.80 confirmed by em	iali (Red 10,0%)
11	ys Of Repair: 2 survey No. of Trip: 1 Survey Fee:
28/4/21-Typist Report Format: Merimen Lump Sum / I.B.I: (\$ 1625.80	Transportation: Site Insp (\$)
×	TOTAL

Lai Huat (Meng Kee) Motor Pte Ltd 160 Sin Ming Drive, #04-01, #04-02 & #07-03, Sin Ming Autocity

575722

Insurer Reference: TP-SJV 890M Repairer Reference: 71671

Date calculated: 03/11/2020 3:42 PM

Full Report Registration: GBH628Z Printed: 03/11/2020 3:42 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

Printed by:

Claim Reference:

Jenny Lim TP-SJV 890M Currency:

(Singapore) Pte Ltd SGD

3.0 LTR 110KW

Estimated Repair Time: Actual Repair Days:

Date of Incident: Hire Car Start: Hire Car End:

28/10/20

Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model: Model Sheet Number:

Registration: VIN number:

Odometer:

SINGLE CAB

Model Specs FROM 01/2017 4366

NISSAN

CABSTAR

71 94 01

GBH628Z

BASE MODEL

AIR CONDITIONING

TWO COAT METALLIC

FOG LAMPS

PREPARE OFF VEHICLE

Not Motional Rewny Bepains

Labour

Labour	Time Base 10 WU/h		Price = 42.00 SGD/h		
Code	Description		wu	Price SGD	
UA10A1)	R + R FRONT BUMPER		6.0	25.20	
UA10A1)	RENEW FRONT BUMPER (REMOVED)		2.0	8.40	
NO NUMBER	R + R TYPE BADGE		3.0	12.60	
RE20A1)	R + R RIGHT HEADLAMP (FRONT GRILLE REMOVED) INCLUDES: REQUIRED COVERS REMOVE AND REFIT.		5.0	21.00	
	ADJUST HEADLAMPS.		2.0	8.40	
NO NUMBER	R + R FRONT VENTILATION GRILLE		3.0	12.60	
NO NUMBER 0900	R + R BADGE NISSAN FRONT PANEL REPAIR		20.0*	84.00	
	Labour Cost	Hrs	wu		
	Panel / Mechanical Labour	4.10	41.0	172.20	
	Total of Labour			172.20	

Audatex System Using Manufacturer Times

Page 1 of 3

PRINT DATE 03/11/2020

aint Work	SYSTEM AZT			Tim	e Basis	10 WU/h
ode	Description - TWO COAT	METALLIC			wu	Price SGD
	FRONT AIR GRILLE NEW PART PAINT K1R FRONT PANEL REPAIR PAINTING <50%			5.0 16.0		
Paint Material	Per Part					
Code	Description					Price SGD
0410 0900	FRONT AIR GRILLE NEW PAR FRONT PANEL REPAIR PAINT					13.28 25.52
	Labour Cost - Paint		42.00.00D //s	Hrs	wu	Price SGD
	Factor Time Paint		42.00 SGD/h		21.0	
	Preparation Main Work Meta	Í		2.50	25.0	105.00
	Preparation Comp. Work Pla			0.50	5.0	21.00
	Total		10 WU/h	5.10	51.0	214.20
	Material Cost - Paint					Price SGD
	New Part Painting - Plastic K	(1R				13.28
	Repair Painting					25.52 28.60
	Material-constant Metal Prep Material-constant Plastic	paration				9.00
	Total					76.40
Spare Parts						- 06 04 /04
Code	Description	Part Number	Part Source	prices as	at 201:	5-06-01/01 Price SGD
0431	BADGE	99081 MB40C	Original			14 28.00
0432	BADGE MODEL	65092 LC65B	Original		n'	th 55.00
0410	FRONT AIR GRILLE	62320 LC60A	Original		By a	11 Cor 275.00
0281	FRONT BUMPER	62022 LC10B KNPL3	Original Original			495.00 0.00
0257	FRONT NUMBER PLATE RIGHT HEADLAMP ASSY		Original		_	m 285.00
0562	KIGHT HEADLAMP ASST	20010 LC03A	Original		C	
f: OEM Parts	Savings					0.00
n: Non-OEM Parts u: Used parts	Subtotal					1,138.00
u. Useu parts	Total					1,138.00
Extras						
Code	Description	-				Price SGD
1000	FRONT NUMBER PLATE Total Extras					<i>B</i> ₄ 35.00*

Audatex System Using Manufacturer Times

Page 2 of 3

PRINT DATE 03/11/2020

Final Calculation

	SGD	SGD
Parts Total Parts	1,138.00	1,138.00
Total Falts		1,130.00
Labour Time Base 10 WU/h Total 41.0 WU X 42.00 SGD/h Total of Labour	172.20	172.20
Total Of Extras		35.00
Paint Work Time Base 10 WU/h Labour Cost 51.0 WU X 42.00 SGD/h Material Cost	214.20 76.40	
Total Paint Including Material		290.60
Repair Cost Excludes GST		1,635.80
GST (+7.0%)		114.51
Repair Cost Included GST		1,750.31

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aloresald.	
	ACCIDENT STATEMENT
Date Of Report	29/10/2020 09:37
Date Of Accident	27/10/2020 08:30
Exact Location Of Accident	BLK 458 HOUGANG AVENUE 10 CAR PARK
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBH628Z
Insured/Policyholder	
Name Of Registered Owner	LIM'S PROVISIONS
Co Reg No	4XXXX000J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63878503
Vehicle Particulars	
Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD
Exact Purpose for which vehicle was being used at time of accident	COMPANY USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800102406-02
Cover Note Number	
Driver	

Driver

Name of Driver

NRIC No

Date Of Birth

LIM SEOW HONG

SXXXX713F

03/06/1958

Date Of Birth 03/06/1958
Occupation INDOOR
Date Of Driving Pass 12/07/1978

Driving Experience 42 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98658968

Fax Number Contact Number

EMail Address NOEMAIL

Page 1 of 14

Address BLK 458 HOUGANG AVENUE 10 #04-409 Postcode 530458 Was driver an employee of the Insured's Company NO If No, Relationship of the Driver with the Insured **OWNER** Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED Weather Conditions CLEAR Road Surface DRY Other Information Was any foreign vehicle involved in this accident? NO Number of vehicles (including own vehicle) involved in the accident 2 Was any body injured in the Accident? NO Was any injured conveyed to hospital by ambulance? NO Was any other material or property damaged? YES I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO Number of Passengers (Including Driver) 0 **Details of Police Action** Was the accident reported to the police? NO If Yes, Please state which Police Station Was notice of intended Prosecution given? NO If Yes, against whom? **Circumstances of Accident** REFER TO SKETCH PLAN. Attachment(s) Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number

SJV890M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

Contact Number

NRIC/Passport Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

PRIVATE CAR

JACQUEN THAM PECK THENG

SXXXX531E

98555248

Brk 458 Hongarp Ave 10 1 A 1 1 Car park Lot B

GN 28/10/2020 about 10 am, my Corny GBH 6287 parkedSationny at BK 458 Horgang par park lot, the front part of my Corry Was found damaged Which was hit my the vehicle. B pls See the photo attched.

The accident was informed by the driver of vertical B and the particular is as below

Driver = 98555248 Driving licence =

Insurer = China Tai Peap.

