LKK Auto Consultants #01-25 Paya Ubi Industrial Park, 51 **Ubi Avenue 1** 408933

Insurer Reference: TP-SJV 890M

Repairer Reference: 71671 Registration: GBH 628Z Date calculated: 28/04/2021 5:20 PM Printed: 28/04/2021 5:21 PM

Summary Information

Claim

Location: Singapore (SG) Work Provider: China Taiping Insurance

(Singapore) Pte Ltd

Full Report

Printed by: KK LAU Currency: SGD Date of Incident: Claim Reference: TP-SJV 890M 28/10/20

Estimated Repair Time: Actual Repair Days:

Hire Car Start: Hire Car End:

Vehicle Details

Vehicle

Manufacturer: NISSAN Model: CABSTAR Sub Model: **BASE MODEL** Model Sheet Number: 71 94 01 **GBH 628Z** Registration:

VIN number:

Odometer: 4366

Model Specs

FROM 01.2017 AIR CONDITIONING FOG LAMPS 3.0 LTR 110KW

SINGLE CAB TWO COAT METALLIC PREPARE OFF VEHICLE


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Labour

Laboui	Time Base 10 \	WU/h	Pri	ce = 42	.00 SGD/h	
Code	Description				Price SGD	
UA10A1)	R + R FRONT BUMPER			6.0	25.20	
UA10A1)	RENEW FRONT BUMPER (REMOVED)			2.0	8.40	
NO NUMBER	R + R TYPE BADGE			3.0	12.60	
RE20A1)	R + R RIGHT HEADLAMP (FRONT GRILLE REMOVED) INCLUDES: REQUIRED COVERS REMOVE AND REFIT. ADJUST HEADLAMPS.			5.0	21.00	
NO NUMBER	R + R FRONT VENTILATION GRILLE			2.0	8.40	
NO NUMBER	R + R BADGE NISSAN			3.0	12.60	
0900	FRONT PANEL REPAIR			20.0*	84.00	
	Labour Cost Panel / Mechanical Labour		Hrs 4.10	WU 41.0	172.20	
	Total of Labour				172.20	
Paint						
Paint Work	SYSTEM AZT			Time Basis 10 WU/h		
Code	Description - TWO COAT METALLIC			WU	Price SGD	
	FRONT AIR GRILLE NEW PART PAINT K1R			5.0		
	FRONT PANEL REPAIR PAINTING <50%			16.0		
Paint Materia	al Per Part					
Code	Description				Price SGD	
0410	FRONT AIR GRILLE NEW PART PAINT K1R				13.28	
0900	FRONT PANEL REPAIR PAINTING <50%			25.52		
	Labour Cost - Paint	42.00 CCD /b	Hrs	WU	Price SGD	
	Factor Time Paint	42.00 SGD/h		21.0		
	Preparation Main Work Metal		2.50	25.0	105.00	
	Preparation Comp. Work Plastic		0.50	5.0	21.00	
	Total	10 WU/h	5.10	51.0	214.20	
		20 110,	5.25	32.3		
	Material Cost - Paint				Price SGD	
	New Part Painting - Plastic K1R				13.28	
	Repair Painting				25.52	
	Material-constant Metal Preparation				28.60	
	Material-constant Plastic				9.00	
	Total				76.40	

prices as at 2015-06-01/01

Code	Description	Part Number	Part Source		Price SGD
0431 0432 0410 0281 0257 0562	BADGE BADGE MODEL FRONT AIR GRILLE FRONT BUMPER FRONT NUMBER PLATE RIGHT HEADLAMP ASSY	99081 MB40C 65092 LC65B 62320 LC60A 62022 LC10B KNPL3 26010 LC65A	Original Original Original Original Original Original		28.00 55.00 275.00 495.00 0.00 285.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal				0.00 1,138.00
u. oscu parts	<u>Total</u>				1,138.00
Extras					
Code	Description				Price SGD
	FRONT NUMBER PLATE Total Extras				25.00* 25.00
Final Calcula	tion				
				SGD	SGD
Parts Total Parts				1,138.00	1,138.00
Labour Time Base 10 WU/h Total 41.0 WU X 42.00 SGD/h 172.20 Total of Labour 172.20					172.20
Total Of Extras					
Paint Work Time Base 10 WU/h Labour Cost 51.0 WU X 42.00 SGD/h Material Cost 76.40 Total Paint Including Material					290.60
	-				1,625.80
Repair Cost Excludes GST					

Comments

* - USER SUPPLIED DATA

Repair Cost Included GST

GST (+7.0%)

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

113.81

1,739.61