

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20012046/T1YD3E2

**Date:** 04/10/2021

### REFERENCE

Insured/Claimant: SANGRAM SINGH Policy No: 1700037162  
Date of Loss: 31/10/2020 Nature of Claim: OD Claim No: 9179437499SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGL367X**  
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN045373  
Reg. Date: 02/09/2017 (Man. Year: 2017) Chassis No: WAUZZZF41JA022724  
Colour: Red Odometer: 22577 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$90,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,319.00	5,475.60	6,843.40	55.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,252.00	9,367.00	8,885.00	48.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,571.00</b>	<b>14,842.60</b>	<b>15,728.40</b>	<b>51.45</b>
<b>- Excess (S\$)</b>	<b>600.00</b>	<b>600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>29,971.00</b>	<b>14,242.60</b>	<b>15,728.40</b>	<b>52.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,097.97</b>	<b>996.98</b>	<b>1,100.99</b>	<b>52.48</b>
<b>Nett Amount (S\$)</b>	<b>32,068.97</b>	<b>15,239.58</b>	<b>16,829.39</b>	<b>52.48</b>

### INSPECTION

Date of Assignment: 04/11/2020

Date Inspected: 03/11/2020 Inspected At:

24 Benoi Sector Singapore 629857  
Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 12.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	2,181.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	72.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	220.00 FS	*- FS
4	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	45.00 FS	*- FS
5	1		*REAR FENDER - RH	Bent	2,644.00 FS	*2,115.20 FS
6	1		*REAR WINDSCREEN	Necessary	1,141.00 FS	*912.80 FS
7	1		*SIDE WINDOW - RH	Necessary	609.00 FS	*486.80 FS
8	1		*PRIMER	Necessary	19.00 FS	*14.96 FS
9	1		*FUEL POCKET	Not Necessary	88.00 FS	*- FS
10	1		*FUEL FILLER CAP	Not Necessary	305.00 FS	*- FS
11	1		*LED TAIL LIGHT - RH	Cracked	1,008.00 FS	*806.40 FS
12	1		*TAIL LIGHT TRIM - RH	Not Necessary	30.00 FS	*- FS
13	1		*WHEEL HOUSING LINER - RH	Not Necessary	237.00 FS	*- FS
14	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
15	1		*LUGGAGE COMPARTMENT TRIM - RH	Not Necessary	779.00 FS	*- FS
16	1		*WHEEL HOUSING - RH OUTER	Not Necessary	625.00 FS	*- FS
17	1		*INNER SIDE PANEL RH REAR	Not Necessary	846.00 FS	*- FS
18	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
19	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
20	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
21	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
22	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*SUNDRIES	Necessary	300.00 FS	*59.44 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 12,319.00 5,475.60**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	New	360.00	0.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	New	600.00	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	New	200.00	200.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	New	1,400.00	1,400.00
7	TO DISMANTLE AND RENEW REAR BUMPER, CUT OUT AND WELD RHS REAR FENDER, RHS OUTER WHEEL HOUSING AND RHS REAR D-INNER SIDE PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	7,700.00	3,000.00
8	TO RESPRAY REAR BUMPER, RHS REAR FENDER, DOOR ENTRANCES, RHS OUTER WHEEL HOUSING AND RHS D-INNER SIDE PANEL, RHS SILL PANEL, FUEL FILLER CAP, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	New	6,000.00	2,575.00
9	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
			<b>Gross Labour Cost (\$\$)</b>	<b>18,252.00</b>
				<b>9,367.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >